Investigation Report for Misalig Glue of Kowa-Emori HP33D1057-1 Carton Box

CONTROL No:	IRF - 0018		REJECT PERCENTAGE:	1.50%			
REJECT QTY:		45	LOT QTY:	3000	REJECT PERCENTAGE.	1.50%	
DIDECT CALICE	W1 Movement of reverse creasing matrix during running.						
DIRECT CAUSE	W2	Weak adh	esion due to	o continuous running.			

PRODUCTION ACTION PLAN

CORRECTIVE ACTION	RE-ORIENTATION REGARDING ON PROCESSING 1 TOUCH MODEL CHECKLIST Re-orientation and strict implementation of Checklist for Processing One Touch Lock Model	PIC:	Production & QA	TARGET DATE:	241204
----------------------	--	------	--------------------	-----------------	--------

PREPARED BY:

APPROVED BY:

GERALD DE GUZMAN
PROD SUPERVISOR

REXEL ALMARIO PROD MANAGER

*** UNCONTROLLED COPY FOR REFERENCE ***



CHECKLIST FOR PROCESSING ONE TOUCH LOCK MODEL

(UPDATED AS OF SEPTEMBER 2024)

	INST	RUCTION	OPERATOR	QA/ME	PROD. LEADE	
		latrix installed in Cutting Plate. Matrix na naka-install sa Cutting Plate. Need Replacement Kailangang Paltan				
Drawing and in	zes of installed "Creas in the correct position.	ing Matrix" in Cutting Plate if match to				
	sa tamang posisyon. Good Maayos	Need Replacement Kailangang Paltan				
	maayos					
Suriin ang no	stalled "Reverse Crea on according to Drawin	e Creasing Matrix" sa Cutting Plate kung				

- ~ Conduct Sampling Checking 1-sheet per batch of 25-sheets in delivery area.

 Magsagawa ng Sampling Checking ng 1-sheet kada bagsak ng 25-sheets sa delivery area.
- $^{\sim}$ Make sure to perform the checklist prior mass production.

Tiyaking naisagawa ang checklist bago ang mass production.

APPROVED BY

MICHAPL CASILIANO QA/ME Asst. Manager REXEL ALMARIO
Prod. Manager