

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)☒ Inhouse Detection☐ Customer Claim

Control No.: 143

Date Issued: 200107

Customer	SANYO DENKI	Attention To	Mr. Gerald De Guzman / Ms. Weena Apalla
Item Code	00665061-01	Department	PRODUCTION
Item Description	PACKAGE	Date of Detection	200106
Job Order Number	WO-19-M-02306-127	Section Detected	QA - SCREENING

ILLUSTRATION OF THE PROBLEM☒ Major☐ Minor

Lot Quantity (pcs.)

Reject Quantity (pcs.)

Reject Percentage

2,240

50

2.23%

Nature of Defect:

BURSTING

Requirement:

No bursting on the smooth surface on the box

Actual:

Bursting on the smooth surface located at the glue tab

NO. OF OCCURRENCE**DISPOSITION****AREA OF OCCURRENCE / ORIGIN****CONTENT**☐ First☐ Hold☐ Slotter☐ Gluing☐ Material☒ Recurrence☐ Special Acceptance☐ EQOS☐ Vertical☐ Dimension

No.: 2nd

☐ For Rework☐ Diecut☒ Others:☒ Appearance

Date: 200106

☒ Reject / Disposal☐ DetachingSEMI-AUTO GLUING☐ Process / Method

Issued by

Checked by

Approved by

Received by
(Receiving Section)

Adrian Vergara
QA-IE Staff

Mr. Roderick Ramos
QA Supervisor

Mr. Rexel Almaro
QA Asst. Manager

Mr. Gerald De Guzman / Ms. Weena Apalla
Head/ Supervisor

I. INVESTIGATION / ANALYSIS**DIRECT CAUSE:** (Analyze the reason of occurrence, why it happened?)**INDIRECT CAUSE:** (Analyze the reason of occurrence, why it leaked?)

System / Training	Why 1:	NOT A FACTOR	Why 1:	NOT A FACTOR
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	
Design / Toolings	Why 1:	NOT A FACTOR	Why 1:	NOT A FACTOR
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	
Process / Material	Why 1: - OPERATOR REPORT THIS PROBLEM TO LEADER AND TRY DIFFERENT ADJUSTMENT IN SETUP OF SEMI AUTO GLUING.	- WE FOUND THAT THE PROBLEM CAUSED IS THE BRITTLINESS OF MATERIALS BECAUSE THE OCCURRENCE OF BURSTING IS RANDOMLY	Why 1: - LEADER APPROVED TO CONTINUE THE PROCESS IN SEMI AUTO GLUING	- BECAUSE MATERIALS ALREADY HAVE PRINT AND WE DONT KNOW HOW MANY ARE AFFECTED BECAUSE BURSTING OCCURS DURING BOX FORM CHECKING IN QA SCREENING.
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**FINAL CONCLUSION****OCCURRENCE ROOTCAUSE****OUTFLOW ROOTCAUSE**

- BRITTLENESS OF MATERIALS

- RANDOMLY OCCURRENCE AND BURSTING
OCCURS DURING BOX FORM CHECKING
IN QA SCREENING.

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)

CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)

A. Sorting Result

Actions to be done to eliminate recurrence

Who / When

	Location	Total Stock	NG	Total Good
RM	N/A			
WIP	N/A			
FG	QA-Inline (Semi-Auto)	2,240	50	2,190

System	N/A	
--------	-----	--

B. Orientation

Date	N/A	Time	N/A
Title	N/A		
Notes	N/A		

Design / Tools	N/A	
----------------	-----	--

C. Reworking

Rework Quantity	N/A
Total Good	N/A
Rework Percentage (Good)	N/A

Process	Attach clearance reference on the gluing applicator to avoid over compression of the WIP during process and also to standardize the setting each material	Prod. (Next Running)
---------	---	----------------------------

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)

Date Conducted: 20 01 08 PIC: A. Vergara

Identified Rootcause

Recommendation

~ Bursting occurs due to tight compression glue
applicator on the materials and brittle surface
of corrugated boards

~ Put clearance reference on the gluing applicator
of the machine to standardize the clearance
for each flute

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked by	Date	Implemented?	Remarks
1st Verification of Action	A. Vergara	20 01 08	[] Yes [X] No	For Follow-up
2nd Verification of Action	A. Vergara	20 01 16	[X] Yes [] No	Corrective Action is already implemented for both Semi-Auto Gluing Machine
3rd Verification of Action			[] Yes [] No	
Effectiveness of Action	A. Vergara	20 03 11	[X] Yes [] No	CA is implemented & effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE

Status:	Remarks:	Approved by:	Process Owner Acknowledgment: (Receiving Section)
☒ Closed	Lot's Running no occurrence of same defect.	 QA Supervisor	 Line Leader
☐ Still Open		 QA Asst. Manager	 Department Head
☐ Re-Issue IRF		Date: 20 07 08	Date: 20 07 13