

564


KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
 Telephone No. (049) 545-7166 to 69
 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)
☒ Inhouse Detection

☐ Customer Claim

Control No.: 199

Date Issued: 20 03 05

Customer	EMORI	Attention To	Mr. Gerald De Guzman / Ms. Weena Apalla
Item Code	HP33D1012	Department	PRODUCTION
Item Description	CARTON BOX	Date of Detection	20 03 04
Job Order Number	WO 20 M 00310 26	Section Detected	QA - SCREENING

ILLUSTRATION OF THE PROBLEM
☒ Major

☐ Minor

Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage
1,992	108	5.42%

Nature of Defect:

Misalign Print

Requirement:

Print should not exceeded on the creasing line

Actual:

Printing is inclined and exceeded on the creasing line

NO. OF OCCURRENCE		DISPOSITION		AREA OF OCCURRENCE / ORIGIN		CONTENT	
☐ First	No.: 5 Date: 20 03 04	☐ Hold	☐ Special Acceptance ☐ For Rework ☒ Reject / Disposal	☐ Slotter	☐ Gluing	☐ Material	☒ Dimension ☒ Appearance ☐ Process / Method
☒ Recurrence		☐ EQOS		☐ Vertical	☒ Dimension		
		☐ Diecut		☐ Others:	☒ Appearance		
				☐ Detaching			
Issued by		Checked by		Approved by		Received by (Receiving Section)	
 Adrian Vergara QA-IE Staff		Mr. Rexel Almario QA Asst. Manager		 Mr. Rexel Almario QA Asst. Manager		 Mr. Gerald De Guzman / Ms. Weena Apalla Head/ Supervisor	

I. INVESTIGATION / ANALYSIS
DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)

System / Training	Why 1:	NOT A FACTOR	Why 1:	NOT A FACTOR
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	
Design / Toolings	Why 1:	NOT A FACTOR	Why 1:	NOT A FACTOR
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	
Process / Material	Why 1:	PLS. SEE ATTACHED	Why 1:	PLS. SEE ATTACHED
	Why 2:		Why 2:	
	Why 3:		Why 3:	
	Why 4:		Why 4:	
	Why 5:		Why 5:	

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**FINAL CONCLUSION****OCCURRENCE ROOTCAUSE**

~ 2 POSSIBLE FACTOR 1ST IS WARP MATERIALS
2ND IS HIGH STACKING OF MATERIALS
AT THE FEEDING UNIT.

OUTFLOW ROOTCAUSE

~ OCCURRENCE IS RANDOMLY AND
THE ITEM IS NOT YET DIE-CUTTED WHY
IS NOT SO VISIBLE.

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**CORRECTIVE ACTION:** (Actions to be done to ensure that the problem will not happen again)**A. Sorting Result**

	Location	Total Stock	NG	Total Good
RM	N/A			
WIP	N/A			
FG	QA-SCREENING	1992	108	1884

Actions to be done to eliminate recurrence**Who / When****System**

N/A

Design / Tools

N/A

Process

PLS. SEE ATTACHED

B. Orientation

Date	20 03 10	Time	10:00 AM - 10:05 AM 7:15 PM - 7:20 PM
Title	Orientation Regarding Misalign Print of HPCOPD2 carton box		
ees	EQAS Operator		

C. Reworking

Rework Quantity	N/A
Total Good	N/A
Rework Percentage (Good)	N/A


II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)Date Conducted: 10 03 09PIC: A. Vergara**Identified Rootcause****Recommendation**

~ Difficulty in feeding unit to draw the materials
because of high stacking height
~ Previous countermeasure where stacking height
should be reduce to 200mm is not strictly followed

~ standardized the stacking height in EQAS machine
feeding unit

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked by	Date	Implemented?	Remarks
1st Verification of Action	A. Vergara	20 03 10	☒ Yes ☐ No	orientation is already conducted
2nd Verification of Action			☐ Yes	
3rd Verification of Action			☐ Yes	
Effectiveness of Action	A. Vergara	10 07 08	☒ Yes	



Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE

Status:	Remarks:	Approved by:	Process Owner Acknowledgment: (Receiving Section)	
☒ Closed				
☐ Still Open			IRISH MAY L. ESTAREJA Line Leader	
☐ Re-Issue IRF		Date: <u>200205</u>	Date: <u>200825</u>	Date: <u>200825</u>

INVESTIGATION REPORT FOR MISALIGN PRINT OF EMORI HP33D1012 CARTON BOX

DIRECT CAUSE PROCESS/MATERIAL	W1 - This item is prone in misalign print because print is very near in creasing line.
	W2 -Item is already processed and no changes found in the machine setting, why we just analyzed the two possible cause of the problem.
	W3 - 1st is the random of warp materials
	W4 - 2nd is the slight delay on the entry of the materials due to high stacking of materials at the feeding unit.


INDIRECT CAUSE PROCESS/MATERIAL	W1 - Trial run approved by QA Patrol, that's why they proceed in mass production.
	W2 - Operator did not notice the misalign print, because possible the occurrence is randomly and the item is not yet die-cutted why is not so visible.

CORRECTIVE ACTION

> Re-orientation regarding 300mm stacking height limit in Egos feeder for this item.

PIC: Production

Target Date: 2003012



> For arrangement of corrective action regarding warp materials.

PIC: Sales, Purchasing, MPD, Warehouse, QA and Production.

EQOS Machine

DATE: _____
SHIFT: _____

A B C D E

REMARKS

4551-eth51大

(trial unit)

* pumas spot. dirt.

11425-1027

2671-0471

thn - shn *

Puncus poor print


6071-1021

send

[illegible]

KANEPACKAGE PHILIPPINE, INC.

SO No.: Sales Order #DRS-20-M-00310
 JO No.: WO-20-M-00310-26
 ISSUED BY: Nene Villanueva
 DATE ISSUED: 26-FEBRUARY-2020
 CUSTOMER: EMORI PHILS.



Light Industry Science Park II,
 National Highway, Calamba, 4027 Laguna
 Tel: (049) 545 7166/67
 Fax: (049) 544-0010

Item Description: HP33D1012 CARTON BOX
 Quantity: 2000 Piece
 Delivery Date: 6-MARCH-2020
 Memo: BK Code: HP33D1012
 Blades: Rack 31-B-41

Material Description	Qty To Be Used	Cut Size	No. of Cuts	Actual Qty Used	DR No.	Supplier	Batch No.	Issued By
645 X 810 BF (TX200/CM125/TX200) for HP33D1012 CASE BOX 0	1020	0	0	1020 0pcs	15743	JS		ONAN 3/3

PROCESS	Finished		GOOD QTY	REJECT QTY			OPERATOR	Remarks
	Date	Time		Trial run	In-house	Supplier		
1.EGGS AP 200303	3/3		1020				JDEAN	
2.DIECUT S1700	3/4		1020				DOMZ NICE	
3.DETACH	3/4		2040				Jan, Mae, Paje, Mavis Elmar, Bryan, Mway	
4.CONVEYOR 1	3/4	1245 1540	2000				HARPER RICKSON AD	
5.LOT NUMBERING	3/4		2000				NUM/KENWO	
6.SCREENING			1857 (bal: 143)					
7.QA BUNDLE	3/05		1442 (4)	175			K. Gallos JIMMIE	confirmator

REJECTION HISTORY

- (A). Occurrence Date: 02/02/19, (B). Problem: Misalign Print, (C). NG Quantity: 58 PCS., (D) Rootcause: Due to warp boards, Uneven size of boards and due to wrong feeding orientation of materials
- (A). Occurrence Date: 07/19/19, (B). Problem: Misalign Print, (C). NG Quantity: 283 PCS., (D) Rootcause: Worn-out parts of the diecut machine
- (A). Occurrence Date: 11/9/2019, (B). Problem: MISALIGN PRINT, (C). NG Quantity: 136 PCS., (D) Rootcause: Misalign Print occur due to warp materials
- (A). Occurrence Date: 12/10/2019, (B). Problem: MISALIGN PRINT, (C). NG Quantity: 289PCS., (D) Rootcause: Slight delay on the entry of the material to the feeding printing unit due to high stacking of materials at the feeding unit
-

NOTES

1. Warp boards should be recondition by IQA and WH Person boards for their guide in feeding orientation
2. The operator should monitor the movement of the print make
3. Separate the warp boards to good materials. Warp Board sh
4. The operator should refer on the stacking height limit attac
- 5.

PR-007-F07

JO Received By (WHSE):

Signature over printed name/Date/Time

JO Returned to (QA):

Signature over printed name/Date/Time

EMORI PHILIPPINES INC.	
Item Code HP33D1012	QUANTITY 10 pcs.
Item Description CASE BOX W/ PRINT	Supplier's QC PASSED
Lot No. / Ref. No. 200304 - 00310-26	INSPECTION RoHS OK
QA-CG580	

the

etup

OUT

NETSUITE