

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

965 ABBY	Fax No. (049) 545-6302							
				FINAL CO	NCLUSION			
	OCCURREN	CE ROOTCAUS	E		OUTFLOW ROOTCAUSE			
- WRONG MACHINE SHITTING					- MISALIGN PRINT IS HARD TO NOTICE VISUALLY BELANGE THE MEMS IS NOT YET DIE-COTTED			
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)						CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)		
A. Sorting Re	esult					Actions to be done to eliminate recurrence	Who / When	
	Location	Total Stock	NG	Total Good				
RM	N/A							
WIP	N/A				System	P/ L		
FG	N/A							
3. Orientation	n							
Date	20 08 06 Time 14:50 v 15:00		Design /	N/A				
Title	DUITA TRANSPORTED AND AND AND AND AND AND AND AND AND AN							
dees								
. reworking								
Rework Quantity		N/A			Process	PLS. SEE ATTACHED		
Total Good		N/A						
Rework Per	k Percentage (Good) N/A							
II. QA	ROOTCAUSE VERIFICATION	ON (To be filled o	out by QA In-	-charge)	Date Conducted	d: 20 08 05 PIC: A: Vergana		
	Identified	d Rootcause			Recommendation			
The material slipped inside the printing machine due to wrong feedgate setup. The materials length deviation is t3mm				achine due	1. Slotter operator should cut the boards for diecut items w/ Imm deviation only 2. Printing operator should abuble check if the material flute in the drawing 4 in the machine are tally			
		III. CORRE	CTIVE ACTION	ON VER <u>IFICATI</u>	ON (To be filled	l out by QA In-charge)		
	Cha	cked by					and the second	

	Checked by	Date	Implemented?	Remarks
1st Verification of Action	A-Vexoara	200806	☑Yes []No	c.A. is implemented
2nd Verification of Action			[]Yes []No	
3rd Verification of Action			[]Yes []No	
Effectiveness of Action	A Vergara	210305	[-]Yes []No	C.A. is effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

	IV. CLOSURE			
POUALITY ASSURANCE DEPARTMENT	Approved by:	Process Owner Acknowledgment: (Receiving Section)		
Still Open Re-Iss & IRF	QA Supervisor QA Assy Manager	Line Leader Department Head		
DATE AND DATE AND	216414 Date: 010414	Date: 2 10414 Date: 2 10414		

INVESTIGATION REPORT FOR MISALIN PRINT OF MITSUMI 19-Y338 A DRT-J583 CARTON BOR R

PROCESS/MATERIAL

W1- Misalign Print occurs because Eqos operator forgot to change the Feed Gate to B-flute.


W2- Feed gate set to C-Flute instead of B-Flute (actual item).

W1- Another factor is uneven cut of corrugated board.

W2- Slotter operator didn't consider that the item have print, why there is 3mm uneven cut in corrugated board.

Note:

During diecut process operator notice the print movement and some uneven board, why the operator immediate inform to Leaders in-charge that time.



W1- Operator proceed to mass production.

W2- Trial run approved by QA Patrol.

INDIRECT CAUSE PROCESS/MATERIAL

W3- Eqos operator didn't notice the uneven board and print movement because according to them during sampling the print is within tolerance and misalign print is hard to notice visually

because the items is not die-cutted yet.

CORRECTIVE ACTION

Orient the Slotter operator once the die-cutted box have print the cutting accuracy of corrugated board is within ± 1 mm dimension tolerance only if possible.

PIC: PRODUCTION TARGET DATE: 200806

Orient the Eqos operator to double check the actual materials flute use vs drawing vs. the flute register in Eqos monitor before proceed to trial run.

PIC: PRODUCTION TARGET DATE: 200806

PREPARED BY:

GERALD DE GUZMAN PROD ASSYL SUPERVISOR APPROVED BY:

WEENA V. ARALLA SR. SUPERVISOR