

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)☐ Inhouse Detection☒ Customer Claim

Control No.: 310

Date Issued: 20 10 07

Customer	CANON	Attention To	Mr. Gerald De Guzman / Mr. Rexel Almario
Item Code	RX1-5781-000	Department	PRODUCTION / QA
Item Description	Z10_CARTON EM	Date of Detection	20 10 07
Job Order Number	See attached file	Section Detected	CUSTOMER - CANON

ILLUSTRATION OF THE PROBLEM

☒ Major		☐ Minor
Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage
3,325	2	0.06%

Nature of Defect:

MISALIGN PRINT

Requirement:

Printing displacement should be within $\pm 5\text{mm}$

Actual:

Characters located on the bottom of the box touches the creasing line

NO. OF OCCURRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN	CONTENT
☒ First ☐ Recurrence No.: _____ Date: _____	☐ Hold ☐ Special Acceptance ☐ For Rework ☒ Reject / Disposal	☐ Slotter ☒ EQOS ☐ Diecut ☐ Detaching ☐ Gluing ☐ Vertical ☐ Others: _____	☐ Material ☒ Dimension ☐ Appearance ☐ Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
 Adrian Vergara QA-IE Staff	 Ms. Noemi Cepeda QA Supervisor	 Mr. Rexel Almario QA Asst. Manager	 Mr. Gerald De Guzman / Mr. Rexel Almario Head/ Supervisor

I. INVESTIGATION / ANALYSIS

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)		INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)	
System / Training	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	
Design / Toolings	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	
Process / Material	Why 1: Why 2: Why 3: PLS - SEE ATTACHED Why 4: Why 5:	Why 1: Why 2: Why 3: PLS - SEE ATTACHED Why 4: Why 5:	

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**FINAL CONCLUSION****OCCURRENCE ROOTCAUSE**

- WARP AND UNEVEN CUT OF SHEETS.

OUTFLOW ROOTCAUSE

- RANDOM OCCURRENCE.

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)**CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)****A. Sorting Result**

	Location	Total Stock	NG	Total Good
RM	N/A			
WIP	N/A			
FG	LAGUNA & FPHP	281	0	281

Actions to be done to eliminate recurrence**Who / When****System**

N/A

B. Orientation

Date	20 10 12	Time	11:40-11:45 PM/11:46-11:49 PM
Title	ORIENTATION REGARDING MISALIGN PRINT OF CBMP RX1-5161-000 Z10 CARTON		
Attendees	EQDS & S1700 OPERATORS		

Design / Tools

N/A

C. Reworking

Rework Quantity	N/A
Total Good	N/A
Rework Percentage (Good)	N/A

Process

PLS. SEE ATTACHED.

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)

Date Conducted: 20 10 12

PIC: A. Vergara

Identified Rootcause

> Misalign print occurred because the corrugated board bump on the printing rollers since the boards are warp
> No visual checking during box forming of QA

Recommendation**III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)**

	Checked by	Date	Implemented?	Remarks
1st Verification of Action	A. Vergara	20 10 14	☒ Yes ☐ No	C.A. is implemented
2nd Verification of Action			☐ Yes ☐ No	
3rd Verification of Action			☐ Yes ☐ No	
Effectiveness of Action	A. Vergara	20 11 14	☒ Yes ☐ No	C.A. is effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE

QUALITY ASSURANCE DEPARTMENT		Approved by:		Process Owner Acknowledgment: (Receiving Section)	
Status:	Remarks:				
☒ Closed	CLOSED	QA Supervisor	QA Asst. Manager	Line Leader	Department Head
☐ Still Open					
☐ Re-Issue IRF					
DATE AND SIGNATURE	Date: 21 01 11	Date: 21 01 11	Date: 21 01 11	Date: 21 01 11	

9/24 No mats

KANEPACKAGE PHILIPPINE, INC.

NETSUITE
QA TRANSFER TO FG
BY: Shane FG 200
DATE: 200930 (6) reject
TIME: 12:02 AM (6) X

200X2



Light Industry Science Park II,
National Highway, Calamba, 4027 Laguna
Tel: (040) 645 7160/67
Fax: (040) 544-0010

SO No.:
JO No.:
ISSUED BY: **WO-TO-IPD-418-4**
DATE ISSUED: **Jhoana de Guzman**
CUSTOMER: **21-SEPTEMBER-2020**
CANON BUSINESS MACHINE PHILS.

Item Description: **RX1-6781-000 Z10 CARTON** Memo: **RX1-5781-000**
Quantity: **600 Piece** BK Code:
Delivery Date: **25-SEPTEMBER-2020** Blades:

Material Description	Qty To Be Used	Cut Size	No. of Cuts	Actual Qty Used	DR No.	Supplier	Batch No.	Issued By
765X1494 EBF NPK280/CM150/TX200 /CM175/NPK280 0	620	0	0	0pcs 620	0140847	PN		unm 9/28

PROCESS	Finished Date	Time	GOOD QTY	Trial Run	REJECT QTY		OPERATOR	Remarks
					In-house	Supplier		
1.EQOS	9/29	9/28	617	10	3		MCTHD	
2.DIECUT S1700	9/29		617	5			MJ.GAM	
3.DETACH	N/A							AUTO STRIP
4.CONVEYOR 1	9/29	9/30	200 + 170 + 217 = 587		13		REU Pick - NA	
5.LOT NUMBERING	9/29		200				Temper/Kusuf	
6.SCREENING	9/29		200				Rodney	
7.QA BUNDLE	9/30		270		16		Jeff	

587

REJECTION HISTORY

(Balanced - 30 pcs)

NETSUITE
QA TRANSFER TO FG
BY: Shane FG 200
DATE: 200930
TIME: 11:45 PM

NOTES

- 1. 200 TRANSFERRED to QA - Charlotte ah.
- 2. 170 Transferred to QA - Anne 9/30
- 3. 217 Transferred to QA - Charlotte
- 5.

PR-001-F07 REV.00

JO Received By (WHSE):
WHOUSE OUT
Signature over printed name/D:
DATE: 9/28

Customer
CANON BUSINESS MACHINES (PHILS.)

Part Code	REV. 00	Inspection Date
		200929
Description	Quantity	QA Inspector
Z10_CARTON EM	200 pcs.	QA-CG233
Job Order Number	Disposition	
	QA PASSED	
* W O - T O - I P D - 4 1 8 - 4 *		IPD RoHS

KANEPACKAGE PHILIPPINES INC

KANEPACKAGE PHILIPPINE, INC.

SO No.:
JO No.:
ISSUED BY:
DATE ISSUED:
CUSTOMER

WO-TO-IPD-418-3.1
Engleberth Dario
28-SEPTEMBER-2020
CANON BUSINESS MACHINE PHILS.

NETSUITE
QA TRANSFER TO FG
BY: Online FG 305
DATE: 201003
TIME: 11:46 PM

Light Industry Science Park II,
National Highway, Calamba, 4027 Laguna
Tel: (049) 545 7166/67
Fax: (049) 544-0010

Let 9/28
next 10/5 waiting
1390 10/1
415

Item Description: RX1-5781-000 Z10 CARTON
Quantity: 305 Piece
Delivery Date: 1-OCTOBER-2020

Memo:
BK Code: RX1-5781-000
Blades:

Material Description	Qty To Be Used	Cut Size	No. of Cuts	Actual Qty Used	DR No.	Supplier	Batch No.	Issued By
765X1494 EBF NPK280/CM150/TX200 /CM175/NPK280 0	325 305 0	0	0	305 0 pcs	40847	PV		Jan 10/3

PROCESS	Finished		GOOD QTY	Trial Run	REJECT QTY		OPERATOR	Remarks
	Date	Time			In-house	Supplier		
1. EQOS	10/3		305				JEN-V	
2. DIECUT S/700	10/3		305				GMLU	
3. DETACH								
4. CONVEYOR 1	10/3		305				REN	
5. LOT NUMBERING	10/3		305				Henry Jeff	
6. SCREENING	10/3		305				Jeff	
7. QA BUNDLE	10/3		305					

REJECTION HISTORY

-
-
-
-
-

- NOTES
- -
 -
 -
 -

PR-001-F07 REV.00

JO Received By (WHSE):
Signature over printed name/Date/Time

JO Returned to (QA):
Signature over printed name/Date/Time

PRODUCTION OUT
BY: Wey
DATE: 10/3
NETSUITE

QUALITY ASSURANCE DEPARTMENT
ENCODER
DATE: 10/3
Angela

SCREENING INSPECTION REPORT (CORRUGATED AND MOULDED ITEMS)

Control No.

SQA-10-000415

I. Item Information

CANON BUSINESS MACHINES (PHILS.), INC.

Customer	CANON BUSINESS MACHINES (PHILS.), INC.				
Location	BATANGAS	Inspection Date	201003	Shift:	☐ Day ☒ Night
Item Code	RX1-5781-000	Delivery Date	201005		
Item Description	Z10 CARTON	Job Order No.	WO-TO-IPD-418-3.1		
Model	N/A	Job Order Qty.	305		
Drawing Revision No.	Rev. 00	Inspection Method	☒ 100% ☐ Sampling		
External Provider	PW	Delivery Receipt No.	K0847		

II. Dimensional Inspection

Time Conducted Sample #1: 18:00			Time Conducted Sample #2: 20:00			Time Conducted Sample #3: 23:00					
Checkpoints	Drawing Specs	Tolerance	Sample #1	Sample #2	Sample #3	Checkpoints	Drawing Specs	Tolerance	Sample #1	Sample #2	Sample #3
1	434	±4	435	435	435	16					
2	270	±3	270	270	270	17					
3	446	±4	445	445	445	18					
4	92	±5	95	95	95	19					
5	32	±5	33	33	33	20					
6	21	±5	20	20	20	21					
7	21	±5	20	20	20	22					
8	21	±5	20	20	20	23					
9	43	±5	43	43	43	24					
10	20	±5	20	20	20	25					
11						26					
12						27					
13						28					
14						29					
15						30					

Measuring Tools

III. Visual Inspection (Leave cell blank if no detection on Applicable Criteria. Ensure to put actual quantity of defect based on classification or "N/A" if Not Applicable)

A. CORRUGATED ITEM / BOX / DANPLA	In-house	External Provider	Total Quantity	B. PALLET	In-house	External Provider	Total Quantity
Scoring				Condition of Wood	N/A	N/A	N/A
Grain Direction				Rusty Nail	N/A	N/A	N/A
Paper Shade (Off Color)				Warping	N/A	N/A	N/A
Bubbles				Fumigation Stamp	N/A	N/A	N/A
Blister				Crack/ Damages	N/A	N/A	N/A
Wrinkle				Others	N/A	N/A	N/A
C. CORRUGATED PALLET	In-house	External Provider	Total Quantity				
Delamination				Color of Carton (Discoloration)	N/A	N/A	N/A
Uneven Kraft liner				Flute of Material	N/A	N/A	N/A
Warpage				Type of Adhesion	N/A	N/A	N/A
Cracking on edge				Adhesion of Runner	N/A	N/A	N/A
Bursting / Bursting on Edge (Crowfeet)				Rusty Wire	N/A	N/A	N/A
Wrong die-cut orientation				Wrong Orientation	N/A	N/A	N/A
Inverted die-cut				Damages: _____	N/A	N/A	N/A
Close Gap/ Wide Gap				Others: _____	N/A	N/A	N/A
Print Color: _____							
Missing Print/ Character							
Blotted Print							
Smeared Print							
Other Print Defect: _____							
Linemark							
Fish-eye							
Stain: _____							
Excess Glue							
Gluing Defect: _____							
Worn-out							
Dent							
Punctured							
Tear-off							
Peel-off							
Damages: _____							
Others: _____							

INVESTIGATION REPORT FOR MISALIGN PRINT OF CBMP RX1-5781-000 Z10 CARTON

DIRECT CAUSE PROCESS/MATERIAL	W1- Base on investigation there are two possible cause of Misalign Print/Diecut, 1st is Warp material and 2nd is uneven cut of sheets.
	W2- Diecut S1700 operator encountered downtime due to ejection error because of warp materials and print adjustment due to uneven cut of sheets.

CONDITION SHEET			S1700 Diecut
Start	End	Time	Machine Breakdown / Downtime / Others
15:00	15:05	05:00	1. Initial Adjust Print & Ejection Trouble in Stripper Area
15:05	15:10	05:05	2. 11 mins. Ejection Trouble
15:10	15:15	05:10	3. 20 mins. Breaktime
15:15	15:20	05:15	4. The Trimming disposal no available from machine
15:20	15:25	05:20	5. The ejection error due to warp materials
15:25	15:30	05:25	6. 15 mins. adjusting print due to uneven sheet cut (clo supplier) and backing tape due to peal of pt slot area.
15:30	15:35	05:30	
15:35	15:40	05:35	
15:40	15:45	05:40	

③	1hr. ejection error due to warp materials
③	15 mins. adjusting print due to uneven sheet cut (clo supplier) and backing tape due to peal of pt slot area.

MACHINE RATIO SHOW THE DOWNTIME ENCOUNTER DUE TO WARP MATERIALS AND UNEVEN CUT OF SHEETS

INDIRECT CAUSE (OUTFLOW) PROCESS/MATERIAL	W1- Operator did not trap the Misalign Print/Diecut during sampling because possible its occurs randomly.
--	--

PRODUCTION CORRECTIVE ACTION

Orient the Egos and Diecut operator regarding this problem and once they encounter Warp or Uneven cut of sheets for this item, immediate inform the leader in-charge and QA for the disposition.


PIC:	PRODUCTION	TARGET DATE:	201009
-------------	-------------------	---------------------	---------------

PRODUCTION CORRECTIVE ACTION


> Review & Orient IQA for tapping procedure during incoming of raw mats

PIC:	QA	TARGET DATE:	201008
-------------	-----------	---------------------	---------------

PREPARED BY:

for: 
GERALD DE GUZMAN
PROD ASST. SUPERVISOR

APPROVED BY:


WEENA V. APALLA
SR. SUPERVISOR

700 DIE CUT


[illegible]

CAUSE OF THE PROBLEM


5M REVIEW	
FACTOR	DETAILS
MAN	NO CHANGE
METHOD	No visual checking during box forming
MACHINE	NO CHANGES
MATERIAL	NO CHANGES
ENVIRONMENT	NO CHANGES

OUTFLOW ROOTCAUSE ANALYSIS:

The QA Inspector did not detected the 2 pieces of misalign print because the QA Inspector did check if the print moved to the creasing since the Inspector focused on checking of ink stain during that time




> Ink stain was located on the upper body of the item




> Misalign print was located on the bottom body of the item

CORRECTIVE ACTION:

1. Conduct Box form appearance checking if the characters located on the upper / lower part of the item touch the creasing line (Box forming appearance will be conducted during box forming dimension checking)
2. Include in the existing Work Instruction the additional checking as reference of QA Inspectors (WI-QA-018-013)
3. Conduct re-orientation to QA Inspector regarding on the additional instruction for misalign printing



BOTTOM PART PRINT CHECKING



UPPER PART PRINT CHECKING

Target Date: October 10, 2020