			E PHILIPPINE INC. a Mesa, Calamba City, Laguna	INVESTIGATION REPORT FORM (IRF)					
	Telephone No. Fax No. (049)	. (049) 545-7166 to 545-6302	69	Inhouse Detection	mer Claim				
	easan gesometer versions			Control No.: 362	Date Issued:	21 01 12			
Customer		EPSON IJP		Attention To	Mr. Gerald De Guzman				
Item Code		5150864-01		Department	PRODUCTION				
Item Desc	ription	INDIVIDUAL B	OX	Date of Detection	21 01 11				
Job Order	Number	WO-DRS-20-L	-0165-7	Section Detected	QA - SCREENING	A COLOR HOLLOW SERVICE SERVICES			
	ILL	USTRATION OF	FTHE PROBLEM	Major	Minor				
				Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
				4500	43	0.96%			
		CREASING	GLINE	Nature of Defect:					
	[11]	PRINTING DIREC	EPSON EXCEED YOUR VISION		MISALIGN PRINT				
	岩			Requirement:					
				Pr	inting position should not be in	clined			
				Actual:					
				2005 T 3 (2004) Act of the Control o	Inclined printing				
	NO. OF OCCURR	ENCE	DISPOSITION	AREA OF OCC	URRENCE / ORIGIN	CONTENT			
	irst		Hold	Slotter	Gluing	Material			
100000	Recurrence		Special Acceptance	EQOS	Vertical	Dimension			
Bounes	lo.: 6		For Rework	Diecut	Others:	Appearance			
	Date: 21 01 11		Reject / Disposal	Detaching		Process / Method			
	Issued by		Checked by	Approved	by	Received by			
	locaca by		Λ Ο		Control of the Property of the Control of the Contr	(Receiving Section)			
/	Adrian Vergar QA-IE Staff		Ms. Noem Cepeda QA Supervisor	Mr. Rexel Aln QA Asst. Mar		Gerald De Guzman			
			I. INVESTIGA	TION / ANALYSIS					
	DIRECT CAUSE: (A	nalyze the reaso	on of occurrence, why it happened?)	INDIRECT CAUS	E: (Analyze the reason of occur	rrence, why it leaked?)			
l _w	Vhy 1:			Why 1:					
in ing A	Vhy 2:			Why 2:					
System / Training	Vhy 3:	N/	'A	Why 3:	MA				
/stem	Vhy 4:			Why 4:					
1975	Vhy 5:			Why 5:					
	Vhy 1:			Why 1:					
sg iii	Vhy 2:			Why 2:					
/ Too	Vhy 3:	A	1/k	Why 3:	P/4				
g	Vhy 4:	•		Why 4:					
	Vhy 5:			Why 5:					
-	Vhy 1:			Why 1:					
	Vhy 2:			Why 2:					
Ma	Vhy 3:	PLS	SEE ATTACHED	Why 3: PS. SEE ATTACHED					
cess	Why 4:	1000		Why 4:					
	Why 5:			Why 5:					

KANEP No. 5 Ring Road Telephone No.

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 5	15-6302						THE RESERVE AND DESCRIPTION	
					FINAL CON	CLUSION			
	0	CCURRENCE	EROOTCAUSE				OUTFLOW ROOTCAUSE		
			WARP 17			- mis	AUGN PRINT OCCURED RANDON	ny	
IMMEDIAT	E ACTION: (A	ction to be done t	to contain/ temporary	correct the pr	oblem found)	CORRECT	IVE ACTION: (Actions to be done to ensure that the problem will not ha	open again)	
A. Sorting Resu	lt						Actions to be done to eliminate recurrence	Who / When	
	Loca	ation	Total Stock	NG	Total Good				
RM	11/1	7				System	MA		
WIP	NIA					- Oysiciii	'/"	E Tour	
FG	N	A							
B. Orientation									
Date			Time			Design /	N/A		
Title						Tools	17/4		
es									
C. Reworking									
Rework Quantity N/A			Process	PLS. SEE ATTACHED					
Total Good			И/А			1,00000	101. 300 111. 20100		
Rework Percentage (Good)			NIA						
II. QA R	OOTCAUSE \	'ERIFICATIOI	N (To be filled oເ	ıt by QA In	-charge)	Date Conduct	ed: <u>21 01 14 PIC: A-Vergara</u>	_	
		Identified	Rootcause				Recommendation		
> Warp ma		rollers	in feeding	unit		> Replace	ment of rubber roller, feeding unit.		
				.,)			6)		
			III. CORREC	CTIVE ACT	ION VERIFICATI	ON (To be fille	ed out by QA In-charge)		

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)								
	Checked by	Date	Implem	nented?	Remarks			
1st Verification of Action	A. Vergara	21 01 17	[/] Yes	[] No	Recommendation is implemented			
2nd Verification of Action	A. Vergara	2101 18	[/]Yes	[] No	C.A. is implemented			
3rd Verification of Action			[]Yes	[] No				
Effectiveness of Action	A. Vergara	21 02 15	· [/]Yes	[] No	Recommendation is effective			

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

		IV. CLOSURE			
THE DEPARTMENT OF DEPARTMENT OF THE PARTMENT O	AFNT	Approved by:	Process Owner Acknowledgment: (Receiving Section)		
A Jacobson Control of the Control of	ate: 2	Supervisor Date: 24 04 14	Line Leader Date: 211414	Department Head	

DATE AND SIGNATURE 21.0

efox .							э».		12/22/2020, 11
ANEPACKA	GE PHIL	IPPINE, INC	C.	A	-10-	27	6 Im	144	
No.: No.: UED BY: JE ISSUED STOMER	EPS	Je	- 26- L - (8-1-20-0165 cille Tuiza CEMBER-20 LIPPINES IN	20 🍝)-IJP 🔎	<i>M</i> !	AP T	ight Industry Science lational Highway, Cali el:(049) 545 7166/67 ax(049)544-0010	Park II. amba, 4027 Laguna
antity: 4500	086401 Individu 0 Piece IANUARY-2021	al Box,PA1			W ₁₁	V)	Memo : BK Code : Blades :	515086401	
A Material Descr		Qty To Cut Si	ze No. of	Actual Qty Used	DR No.		Supplier	Batch No.	Issued By
X918MM CF TX200/0	CM125/TX200 0		0	Opcs wi	14989	5	TS	100	ia rol
PROCESS	Finished	GOOD QTY	Trial Run	RE In-house	JECT QTY	ıpplier	OPERATO	PR .	Remarks
goszandio	Date Tin	7759	5	/		ррисі	CEBBG		
TERNA ALIONO SEMI AUTO GLUING		1038 1221 4452	5			-	85B Man/ranc		
OT NUMBERING	01/11	45 W				- 32	Dane Uin	nwell	
QA BUNDLE	01/11	(390) 405	*	97 55		KAN -	Kanepackage F	0.10	notes de
(A). Occurrentlue on the glue on the glue pplicator controlor. (A). Occurrentloose immedication. (A). Occurrentle print of the peding unit excurrentle.	os ng gluin ce Date: 8/8 tab overflo oller is wor ce Date: 8/1 ce Date: 8/1 item is slar ceded on t ce Date: 8/2	ng operator and a graph of the count of the	oblem: C creasing blem: GL che applic oblem: D ccidenta QA did n oblem: N materials t	OL Lot No.: OL Qty.: Remarks:	FIXANP SISOBE KANO16	ROH	10437729 10437729 102	Nai	R4141691 me: 4 (SILANE) INDIVIDUA L
he materials us and the applied	sed are war	p and the pape	er weight	jig usea s ly)	ilos em	1.1	TO SURE		
. itupi ng maig 2. Clean immed	i ang creas	ing ng aytem a	t ang agy	NOTES wat ng flap	ay 6mn	n DAT	E: 21011120	5 RA KELL	CBOK -

1. 1. Recondition the warp boards using paper weight jigs 2. Separate warp & flat boards 3. Stacking height imit is 600mm 5. 1. Separate the warp boards to not warp boards for separate setup 2. Weight jigs should not be applied on the center of the boards also consider the both ends on- shartotte TRANSFERRED 2R-001-F07 REV.00

JO Received By (WHSE):

oroduce

JO Returned to(QA):

INVESTIGATION REPORT FOR MISALIGN PRINT OF EPSON IJP 5150864-01 INDIVIDUAL BOX

	W1 - During mass production misalign print occurs randomly since only 43pcs out of 4,500pcs or 0.96% are affected.
DIRECT CAUSE PROCESS/MATERIAL	W2 - Possible random of warp materials are included in the materials that was issued in Eqos.
	W3- Warp materials bumps into the feeder gate and roller of EQOS that causes delay in timing and misalign during feeding of materials.

INDIRECT CAUSE (OUTFLOW)

W1 - Operator did not trap the misalign print during sampling since it occurred randomly and only sampling are required during Eqos printing.

PRODUCTION CORRECTIVE ACTION

Orient the Eqos operator that once they trap warp material:

- Immediate separate the raw materials once have warpage.
- Recondition the warp materials using paper weight jig.
- Inform the Leader in-charge regarding warp materials to spread out the information to the concern department.

PIC: PRODUCTION TARGET DATE: 210114

PREPARED BY:

GERALD DE GUZMAN PRODASST. SUPERVISOR APPROVED BY:

MEENAV. APALLA
SR. SUPERVISOR