
5M + 1 REVIEW


FACTORS	DETAILS				
, MAN	no changes				
MACHINE	Movement from sheet stopper due to loosed thread				
METHOD	NO CHANGES				
MATERIAL					
MEASUREMENT	NO CHANGES				
ENVIRONMENT	NO CHANGES				

I. INVESTIGATION / ANALYSIS												
	DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)					ned?)	INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)					
System / Training	Why 1:	y 1:					Why 1:					
	Why 2:	y 2:					Why 2:					
	Why 3:	3: N/A					Why 3:		N/A			
Syster	Why 4:	Control and Art Control					Why 4:					
0,	Why 5:	ıy 5:					Why 5:					
s	t!	thy 1: Scratches occured due to direct contact of panels with the sheet stopper of the machine. Defect were only visible on the blue part of the item. Factor added, blue part of panel are feeded first.					Why 1:					
Design / Toolings	Why 2:	y 2: Sheet stopper has movement (downward) during running					Why 2:		N/A			
J / ug		, allow tropped that the remain (action and) as migretiming					Why 3:		N/A			
Design		y a movement were due to the losse thread of the stopper.										
	Why 4:	4:					Why 4:	hy 4:				
	Why 5:						Why 5:					
<u></u>	Why 1:								apping due to overlooking. Increased number of			
Process / Material				N/A				defect occure	were due to trial of corrective action done during ence.			
l/sse	Why 2:						Why 2:					
Proc							Why 3:					
						FINAL CON	ICLUSIO	N				
	OCCURRENCE ROOTCAUSE						OUTFLOW ROOTCAUSE					
Contact between panels and sheet stopper due to loose thread.					Late trapping due to overlooking.							
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)					CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)							
A. Sorting Result							Actions to be done to eliminate recurrence	Who / When				
		Locat	ion	Total Stock	NG	Total Good	System					
RM		N/A	١						N/A			
WIP		N/A	١						IN/A			
FG		N/A	4									
B. Orie	entation								Alconoli, a condicate at the contract of the	Engineerin		
Date	6	April 11, 2022 Time			Desig		Already coordinated to engineering for checking.	g				
Title		Morning meeting (Reminder of proper inspection in each position)				Tools		Target Date: April 8, 2022				
Atter	Attendees All staff and operators											
C. Re	C. Reworking								Operator positioned both etapper as the other			
Rework Quantity N/A					Process		Operator positioned both stopper on the other side (with white design) to remove scratches					
Total Good N/A				Proce	e55	and perform trial to prevent misalignment.						
Rework Percentage (Good) N/A												
							Date Co	onducte	ed: PIC:			



Actual stopper with tape to temporarily controll movement

IRF- 04-0004 SCRATCHES



Lock temporarily by cable tie to avoid movement. STATUS: Tentative date for cheAPRIL 27 or 28, no running