

**KANEPACKAGE PHILIPPINE INC.**


No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)☒ Inhouse Detection☐ Customer Claim

Control No.: 396

Date Issued: 21 03 08

Customer	NIDEC SUBIC	Attention To	Mr. Gerald De Guzman
Item Code	VR-B	Department	PRODUCTION
Item Description	BOX	Date of Detection	21 03 06
Job Order Number	JO-21-IPD-00071-2	Section Detected	QA - SCREENING

ILLUSTRATION OF THE PROBLEM

<input type="checkbox"/>	Major	<input checked="" type="checkbox"/>	Minor
Lot Quantity (pcs.)		Reject Quantity (pcs.)	Reject Percentage
932		113	12.12%
Nature of Defect:			
MISALIGNED DIE-CUT			
Requirement:			
Customer's logo should not be cut			
Actual:			
Cut Nidec Logo			

NO. OF OCCURRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN	CONTENT
<input checked="" type="checkbox"/> First <input type="checkbox"/> Recurrence No.: _____ Date: _____	<input type="checkbox"/> Hold <input type="checkbox"/> Special Acceptance <input type="checkbox"/> For Rework <input checked="" type="checkbox"/> Reject / Disposal	<input type="checkbox"/> Slotter <input type="checkbox"/> EQOS <input checked="" type="checkbox"/> Diecut <input type="checkbox"/> Detaching <input type="checkbox"/> Gluing <input type="checkbox"/> Vertical <input type="checkbox"/> Others: _____	<input type="checkbox"/> Material <input checked="" type="checkbox"/> Dimension <input type="checkbox"/> Appearance <input type="checkbox"/> Process / Method
Issued by	Checked by	Approved by	Received by (Receiving Section)
 Adrian Vergara QA-IE Staff	 Ms. Noemi Cepeda QA Supervisor	 Mr. Regal Almario QA Asst. Manager	 Mr. Gerald De Guzman Head/ Supervisor

I. INVESTIGATION / ANALYSIS

DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)		INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)	
System / Training	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	
Design / Toolings	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	Why 1: Why 2: Why 3: N/A Why 4: Why 5:	
Process / Material	Why 1: Why 2: Why 3: PLS. SEE ATTACHED Why 4: Why 5:	Why 1: Why 2: Why 3: PLS. SEE ATTACHED Why 4: Why 5:	

**KANEPACKAGE PHILIPPINE INC.**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)**FINAL CONCLUSION****OCCURRENCE ROOTCAUSE****OUTFLOW ROOTCAUSE**

- SUPPLY SURFACE OF WHITE KRAFT MATS.

- RANDOMLY OCCURRENCE

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)

CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)

A. Sorting Result**Actions to be done to eliminate recurrence****Who / When**

	Location	Total Stock	NG	Total Good			
RM	N/A				System	N/A	
WIP	N/A						
FG	N/A						

B. Orientation

Date	N/A	Time	N/A		Design / Tools	N/A	
Title		N/A					
Issues		N/A					

C. Reworking

Rework Quantity	N/A			Process	PLS. SEE ATTACHED	
Total Good	N/A					
Rework Percentage (Good)	N/A					

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)

Date Conducted: 21 03 14 PIC: A. Vergara

Identified Rootcause**Recommendation**

> The materials slip on the printing machine's roller because the boards are smooth

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked by	Date	Implemented?	Remarks
1st Verification of Action	A. Vergara	21 03 14	[X] Yes [] No	C.A. is implemented
2nd Verification of Action			[] Yes [] No	
3rd Verification of Action			[] Yes [] No	
Effectiveness of Action	A. Vergara	21 07 14	[X] Yes [] No	C.A. is effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE


QUALITY ASSURANCE DEPARTMENT	Approved by:	Process Owner Acknowledgment: (Receiving Section)	
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Still Open <input type="checkbox"/> Re-issue IRF	<input checked="" type="checkbox"/> QA Supervisor Date: 21 07 14	<input checked="" type="checkbox"/> QA Asst. Manager Date: 21 07 14	<input checked="" type="checkbox"/> Line Leader Date: 21 07 14 <input checked="" type="checkbox"/> Department Head Date: 21 07 14

DATE AND
SIGNATURE

21 07 14

INVESTIGATION REPORT FOR MISALIGN PRINT OF NIDEC SUBIC VR-B BOX

DIRECT CAUSE PROCESS/MATERIAL	W1- Operator in Eqos concern that the white kraft is prone to misalign due to slippery surface.
	W2- Possible that the sheet slide during printing since during checking of actual reject the print was slanted.



No Suteban in Cyrel Mylar because the sheet size is more than 500mm in height.

INDIRECT CAUSE (OUTFLOW) PROCESS/MATERIAL	W1- Misalign print did not visible since the machine speed is 130bpm and the items is not yet die-cutted.
	W2- Eqos operator did not notice the misalign print during sampling since the occurrence is randomly.

PRODUCTION CORRECTIVE ACTION

Put Suteban in both side of Cyrel Mylar for better grip of sheets even the sheet size is more than 500mm in height, since the white kraft according to Eqos operator is slippery why it is prone to misalign.

PIC:	PRODUCTION	TARGET DATE:	NEXT RUNNING
-------------	-------------------	---------------------	---------------------


PREPARED BY:

210309
GERALD DE GUZMAN
PROD ASST. SUPERVISOR

APPROVED BY:


[Signature]
WEENA V. APALLA
SR. SUPERVISOR

UPDATES:




REMARKS: Sutureban was not mount end to end.

BEFORE



No sutureban on both ends

AFTER



With sutureban on both ends