No. 5 Ring Road	PACKAGE PHILIPPINE INC. d LISP II, Brgy. La Mesa, Calamba City, Laguna (049) 545-7166 to 69 45-6302	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim					
		Control No.: 466	Date Issued:	210915			
Customer	SANYO DENKI PHILS. INC.	Attention To	Attention To Mr. Gerald De Guzman				
Item Code	00949344-01	Department Production					
Item Description	PRINT SPECIFICATION	Date of Detection	210	914			
Job Order Number	JO21-M-01485-125	Section Detected	SD 1800 dy QA-SC	reening			
ILLU	ISTRATION OF THE PROBLEM	Major	Minor				
		Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
WINDS OF THE PARTY	annual transfer and the state of the state o	3,500	334	9.54%			
	M16 0125	Nature of Defect:					
e to il	12 13 14 15		MISALIGN PRINT				
		Requirement:					
		should be 8mm distance from creasing line to the print with a print tolerance of +/- 3mm					
		Actual:					
		E	Exceed the print tolerance by 11mm				
NO. OF OCCURRE	NCE DISPOSITION	AREA OF OCCU	JRRENCE / ORIGIN	CONTENT			
First	Hold	Slotter	Gluing	Material			
Recurrence	Special Acceptance	EQOS	Vertical	Dimension			
No.: 4TH	For Rework	Diecut	Others:	Appearance			
Date: 210914	Reject / Disposal	Detaching		Process / Method			
Issued by	Checked by	Approved b	y	Received by (Receiving Section)			
Rochelle Evangel QA-IE Staff	/ Mlaw	Rexel Alman QA Asst. Mana	io	210916 Serala De Guzman Head/ Supervisor			
	and the state of t	ATION / ANALYSIS					
DIRECT CAUSE: (Ar	nalyze the reason of occurrence, why it happened?)		: (Analyze the reason of occur	rence, why it leaked?)			
Why 1:		Why 1:					
	1/1	Why 2:					
System / Training Myh 4: Myh 3:	N/A	Why 3:	MA				
Why 4:		Why 4:					
Why 5:		Why 5:					
Why 1:		Why 1:					
Why 2:		Why 2: Why 3: Why 4:					
Why 2: Why 3: Why 4:	P/A						
.03 Se	•						
Why 5:		Why 5:					
Why 1:		Why 1:					
Why 2: Why 3: Why 4:		Why 2:					
Why 3:	PLS. SEE ATTACHED	Why 3:	Why 3: P.S. SEE ATTACHED				
Why 4:		Why 4:		*			
Why 5:		Why 5:					

N TO

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 545-6302							
FINAL CONCLUSION								
OCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
- WARP MATERIALS			- RANDOMLY OCCURRENCE					
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)			CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Resi	ult (- 14 - 15)				Actions to be done to eliminate recurrence Who / When			
	Location	Total Stock	NG	Total Good				
RM	N/A				System	ν/,		
WIP	SD1800	3,500	173	3,327	Oystein	P/A		
FG	QA -SCREENING	4,000	1860	3,814				
B. Orientation								
Date	N/A	Time	NIA		Design /	N/		
Title	N/A				Tools	P/4		
Attendees	N/A							
C. Reworking								
Rework Quar	ntity	N	/A		Process	PLS. SEE ATTACKED		
Total Good			I/A					
Rework Percentage (Good)								
II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)				-charge)	Date Conducted: 21 to 17 PIC: A. Vercora			
Identified Rootcause					Recommendation			
The material used has a random occurrence of warp.			Recondition the materials by staggered piling & laying of weight jigs.					

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)								
	Checked by	Date	Implemented?		Remarks			
1st Verification of Action	A. Yergara	21 09 17	[]Yes	[] No	Recommendation is implemented			
2nd Verification of Action	A. Vergara	21 09 21	[] Yes	[] No	O.A. will not pursue since the GPR will decrease			
3rd Verification of Action			[]Yes	[] No	140			
Effectiveness of Action	A. Vergara	21 11 02	[**Yes	[] No	Recommendation is effective			

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.


IV. CLOSURE								
C=Status:	THE A DOLL REMARKS DEDADTA CALL			oved by:	Process Owner Acknowledgment: (Receiving Section)			
(gseur University of the control of	JITY ASQUIVANUE DE TAKTIV	CIVI	A Supervisor	QA Asst Manager	IRISH MAY L. ESTAREJA Line Leader	Department Head		
Re-Issue IRF		Date:	111 03	Date: 21 11 D3	Date: 21 11 03	Date: 21 11 03		
DATE AND						/		


INVESTIGATION REPORT FOR MISALIGN PRINT OF SANYO DENKI 00949344-01 PRINT SPECIFICATION

DIRECT CAUSE PROCESS/MATERIAL

W1- Eterna operator encounter machine error in feeder due to Warp Materials.

W2- There's a factor that due to warp materials there is movement happened in printed sheet during Eterna process that caused misalignment.





INDIRECT
CAUSE
(OUTFLOW)
PROCESS/MATERIAL

W1- Even the operator notice the movement during sampling it is within the ± 3 mm tolerance they did not trap the worst misalignment during sampling since the occurrence is randomly.

PRODUCTION CORRECTIVE ACTION

From 3-outs to 1-out since the 00949344-01 is common to 00902009-01. The 00902009-01 used 1-out cyrel and die-blade as counter measure to misalign print since the big sheets is prone in warpage and in almost a year no occurrence of misalign print in Sanyo Denki 00902009.

PIC:

PRODUCTION

TARGET DATE:

TO BE DISCUSS IN 4PM MEETING

PREPARED BY:

GERALO DE GUZMAN PROP ASST. SUPERVISOR APPROVED BY:

WEENA V. APALLA SR. SUPERVISOR

Short size 3 outs = ?] BF