KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302		INVESTIGATION REPORT FORM (IRF) Inhouse Detection				
Customer	СВМР	Attention To	Mr. Gerald De Guzman			
Item Code	FX2-5524-000	Department	Production			
Item Description	Z10 BOX OUTER	Date of Detection 211110				
Job Order Number	JO-F-21-332-7	Section Detected				
ILLU	STRATION OF THE PROBLEM	Major	Minor			
		Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage		
		1100	50	4.55%		
		Nature of Defect:				
		PEEL OFF				
TEAT		Requirement:				
7		NO PEEL OFF				
		Actual:				
		OCCURRENCE OF PEEL OFF				
NO. OF OCCURREN	NCE DISPOSITION	AREA OF OCCU	IRRENCE / ORIGIN	CONTENT		
First	Hold	Slotter	Gluing	Material		
Recurrence	Special Acceptance	EQOS	Vertical	Dimension		
No.:	For Rework	Diecut	Others:	Appearance		
Date:	Reject / Disposal	Detaching		Process / Method		
Issued by	Checked by	Approved by	,	Received by (Receiving Section)		
	/ha Oau			I I I I		
	/ M Jaw	Tomanus Ly				
Rochelle Eve ngelis QA-IE S taff	Roderick Ramos QA Supervisor	Rekel Almari QA Asst. Mana		erald/De Guzman lead/Supervisor		
V V		TION / ANALYSIS				
DIRECT CAUSE: (Ana	alyze the reason of occurrence, why it happened?)	232 (2015) (2310) 349 (1410) 2100	: (Analyze the reason of occurr	ence, why it leaked?)		
Why 1:		Why 1:	7			
		Why 2:				
System / Training Myhy 3: Why 4:	. 1.	Why 3:	NA			
Why 4:	MA	Why 4:	7.7			
Why 5:		Why 5:				
Why 1:		Why 1:				
		Why 2:				
::: vviiy 2.	N /,					
L D	Pla	Why 3:				
		Why 4:				
Why 5:		Why 5:				
Why 1:		Why 1:				
Myh 5:	PIC COT ATTICK	Why 2:				
8	PLS. SEE ATTALLIED		SEE ATTACKE	D		
557		Why 4:				
Why 5:		Why 5:				

DATE AND **SIGNATURE**

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna

INVESTIGATION REPORT FORM (IRF)

Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302						. ()			
	0	CCURRENCE ROOTCAUS	E			OUTFLOW ROOTCAUSE			
- GAP FROM CUTTING ON CHEKSING BLADE			- ITEM PROCESS/PIEWT IN OPPOSITE SIDE OR POVGH SURFACE.						
COLLECT SMALL SCRAP THAT EPPECE									
IN CUTTING PERFORMANCE.									
IMMEDIATE ACTION; (Action to be done to contain/ temporary correct the problem found)			CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)						
A. Sorting Result				Actions to be done to eliminate recurrence	Who / When				
0.000000	Loca		NG	Total Good					
RM	N	/A			System	N/A			
WIP		<u>/fi</u>				/4			
FG	N	/A							
B. Orientation		1-	T	a					
Date		J/A Time N/A		A	Design / Tools	W/br			
Title		N/A			10013				
Attendees		NIA					-		
C. Reworking			Process	PLS. SEE ATTAMED	(a)				
Rework Quantity N/A									
	Total Good N/A				-	1			
Rework Percentage (Good)				D-4- 044	-1.76.46.57 pp. 0. Vo.20012				
			Date Conducted: 21 11 12 PIC: A - Vergoro						
Identified Rootcause				Recommendation					
there was an unout liner because the gap on the blade started to develop.									
"TO DIAGO STATION TO GOV CIOP.									
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)									
	Asias i Afrika Mandas di Kalamatan di Kalamatan di Kalamatan di Kalamatan di Kalamatan di Kalamatan di Kalamat Kalamatan di Kalamatan di Kalama		ented?	Remarks					
1st Verification	on of Action	A. Vergara	21 11 13	[- Yes	[] No	C.A. is implemented			
0-41/ 15									
2nd Verification of Action				[] Yes	[] No				
3rd Verification of Action				[] Voc	[]No				
ord verification	on of Action			[] Yes	[] No				
Effectivenes	s of Action	A. Vergara	21 11 25	[~] Yes	[] No	C.A. is effective	8		
			- 11 60			/4 offootive			
Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.									
William William									
IV. CLOSURE Approved by: Process Owner Acknowledgment: (Receiving Section)									

Was

11 11 25

21 11 25

Supervisor

Date: 21 11 25

Department/Head

21 11

IRISH MAY L. ESTAREJA Line Leader

Date: 21 11 25

INVESTIGATION REPORT FOR PEEL OFF OF CBMP FX2-5524-000 Z10 BOX OUTER

DIRECT CAUSE PROCESS/MATERIAL

W1- There is a gap from cutting to creasing line blade where the small scrap accumulated during mass production. The accumulated scrap in the gap of cutting and creasing blade effect in the cutting performance of cutting blade and because the item is underwent auto stripping in Diecut S1700 it caused Peel Off to the items.

W2- Possible the gap is due to the hardness of materials (CBF NPK280) and during mass production the small scrap accumulated on that gap.



INDIRECT CAUSE (OUTFLOW) PROCESS/MATERIAL

W1- Operator did not notice the Peel Off since the item cut in opposite side or rough surface and only top portion per batch-pile are conducted sampling since the item is heavy.

PRODUCTION CORRECTIVE ACTION

Repair of Diecut blade c/o Tooling custodian

PIC: PRODUCTION TARGET DATE: 211113

PREPARED BY:

GERALD DE GUZMAN PROD ASST. SUPERVISOR APPROVED BY:

WEENA V APALLA SR. SUPERVISOR



THERE WAS A GAP BETWEEN THE CREASING LINE AND THE CUTTING BLADE.



THE GAP BETWEEN THE CUTTING BLADE AND CREASING RULE IS CORRECTED.