

13-Jan-23

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:
W D717		
K.DIAZ		
OΔ-IF/ Prodn IF	OA/ Prodn SV	KPI IMA Operations Gen. Mngr

5M REVIEW		DOCUMENT REVIEW					
MAN	NO CHANGES	Affected Document:	Date Reviewed:	Disposition:		PIC:	Target Date:
MACHINE	NO CHANGES	Procedure Manual		☐ With Revision	☑ No Revision		
MATERIAL	NO CHANGES	Work Instruction		☐ With Revision	✓ No Revision		
METHOD	NO CHANGES	Process Flow		With Revision	No Revision		
ENVIRONMENT	NO CHANGES	Forms		☐ With Revision	No Revision		

I. PROBLEM DESCRIPTION

DATE:

	1.1. ISSUE:					
	MISALIGNED CUT					
	1.2. ITEM DESCRIPTION:					
	PART CODE:	516297700				
	PART NAME:	LOUVRE MINI MDX ASIA				
1.3. BACKGROUND:						



DETAILS:

>Inhouse Detection: Misaligned cut

>Lot size: 2100pcs > Reject Qty: 55pcs >Rejection Rate: 2.62%

>JO#: 28669

I. IMMEDIATE ACTION						
	ACTION ITEMS	Target Date:	Person In-charge			
	_	-				

III. WHY WHY ANLYSIS DETAILS:


- **DIRECT CAUSE:**WHY 1: Misaligned cut occurred on the upper flap with excess with background on the blue background.
 WHY 2: On trial, there is no misaligned cut encounter but during mass production, the defect comes up.
 WHY 3: In the middle of processing, the operator encountered excess single face and printed sheet on the item.
 - > Having the encountered issue, on the first process in the lamination, operator should check the set-up of items during running.





IV. ACTION PLAN:

DIRECT CAUSE:





DIECUT FEEDER ARE



DIECUT PROCESS (FEEDER AREA)