KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy, La Mesa, Calamba City, Laguna Telephona No. (1992) 545-3455 b. 69.		c. INVESTIGA	INVESTIGATION REPORT FORM (IRF)			
Telepho	one No. (049) 545-7166 to 69 . (049) 545-6302	Inhouse Detection	n Custo	mer Claim		
		Control No.: 229	Date Issued:	20 06 26		
Customer	CANON	Attention To	Mr. Gerald De Guzman / Ms	s. Weena Apalla		
Item Code	FX2-5097-000	Department	PRODUCTION			
Item Description	Z10_BOX OUTER	Date of Detection	20 06 25			
Job Order Number	WO-F-20-M-053-2	Section Detected	CUSTOMER - CBMP			
	ILLUSTRATION OF THE PROBLEM	Major	Minor			
	I II	Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage		
a light and a ligh	FRAGILE WHILE	960	1	0.10%		
Canon [[[[Y]]]]	Canon (IIII)	Nature of Defect.				
TOTAL REPORT	TE NO		WEAK GLUE			
Joseph State of		Positive 4				
		Requirement:				
WEAK	GLUE N	No.	o occurrence of weak on both glu	e tab		
		Actual:				
			The other glue tab has week glu	le .		
NO. OF OCCU	JRRENCE DISPOSITION	AREA OF OCC	URRENCE / ORIGIN			
First	Hold	Slotter		CONTENT		
Recurrence	Special Acceptance	EQOS	Gluing	Material Natural		
No.:	For Rework	Diecut	Others:	Dimension		
Date:	Reject / Disposal	Detaching	The second secon	Appearance Process / Method		
Issued	by Checked by	Approved b	by.	Received by		
~~	2.1.	4		(Receiving Section)		
Adrian Ve	rgara	Mr. Rexel Alm	-//	Gyzman / Msr. Weena Apalla		
QA-IE S	taff QA Supervisor	QA Asst. Mana		ad/ Supervisor		
	I. INVESTIG	SATION / ANALYSIS				
DIRECT CAUSE	(Analyze the reason of occurrence, why it happened?)	INDIRECT CAUSE	: (Analyze the reason of occurre	nce, why it leaked?)		
Why 1:		Why 1:				
ଅଧି	N. /	Why 2:				
System / Training Myh 3: Why 3: Why 4:	NA	Why 3:	MA			
Why 4:		Why 4:	1			
Why 5:		Why 5:	n in a select place the	505		
Why 1:		Why 1:	Take a second and the	13		
Why 2: Why 3: Why 4:	N/	Why 2:				
Why 3:	1/A	Why 3:	N/A			
The second second second		Why 4:	/ 1			
Why 5:		Why 5:				
Why 1:		Why 1;				
Why 2:	PLS. SEE ATTACHED	Why 2:	Commen			
My 3: Why 4:	11110100	Why 3: 723.	SEE ATTAC	HED		
Why 5;		Why 4:				
1, 0,		Why 5:				



KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telaphone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

		Marketin Andreas (1997)						
					FINAL CO	NCLUSION		
N. Carlotte	(OCCURRENC	E ROOTCAUSE				OUTFLOW ROOTCAUSE	
# # KVE 2 77	PETISONS HET PORTING	ENCE E SHIME ON ALKER OR	OF WEAK IN CONV ADY DIVIED to contain/tempora	GLUE FYOR- ? BEFORE	BECAUSE 2 POSSIBLE FEED IN	PE IS C	ON-INED IN GLUING BECA CON-INED IN GLUING BECA CON-INE BA #551 EN TO CHECK EDING OF HEM IN CONVEYORD	AFTER.
A. Sorting Res	sult						Actions to be done to eliminate recurrence	Who / When
	Loca	ation	Total Stock	NG	Total Good			
RM	NI	A					N/	
WIP	QA-INI	INE	200	19	181	System	N/4	
FG	KP- FP	IP	115	0	116			
B. Orientation								
Date	20 06	26	Time	5:45 P.N	N6:00 P.M.	Design / Tools	12/2	
Title	FX2-50	97-000	WEAK BLU					
A ees	QA Insp	ector						
C. Reworking		1,40						
Rework Quantity 19 PCS .						Process PLS. SEE ATTACH	PLS. SEE ATTACHED	
Total Good 19 PCS . Rework Percentage (Good) 100 %					personal and a securitarium is bushessed on a plantonistic and commission of			
II. QA F	ROOTCAUSE V	ERIFICATION	(To be filled o	ut by QA In-	charge)	Date Conducte	ed: 10 06 30 PIC: A Vengara	
		Identified F	407147777				Recommendation	
The glue because because feeding ~ QA Insp fest	e tak wa the item two oper to convey bector con	s not co was do actors gl or: aducts o	ompressed elayed in ue simulta only 1pc. (immedi feedino neously of destr			le waiting time in using glving 2 will use convexor & Operator 1 e destructive test from 1pc. to 3pm templementation of 120° pre-folding	

	III. CORF	RECTIVE ACTIO	N VERIFICAT	ION (To be fill	led out by QA In-charge)
	Checked by	Date	Implemented?		Remarks
1st Verification of Action	A-Vergara	2006 30	[]Yes	[/] No	~ Eliminating walting time in conveyor is done clout under study) ~ Increase destructive test-for revision of W
2nd Verification of Action	A Vergara	20 07 05	[/] Yes	[] No	C.A. & Recommendation is implemented
3rd Verification of Action			[]Yes	[] No	
Effectiveness of Action	A Vergara	20 07 16	[] Yes	[] No	C.A. A Recommendation is effective

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, investigation Report shall be re-issued to the affected department to provide new improvement action.

	IV. CLOSURE	
NEW QUALITY ASSURANCE DEPARTMENT	Approved by:	Process Owner Acknowledgment: (Feceiving, Section)
Still Open	Supervisor QA Set Manager	Line Leader Department Head
DATE AND SIGNATURE 21 04 14	2/04/4 Date: 2/04/14	Date: 210414 Date: 210414

INVESTIGATION REPORT FOR WEAK GLUE OF CBMP FX2-5097-000 Z10 BOX OUTER

	W1- Lack of compression in the portion that have occurrence of weak glue.
	W2- Possible the glue on that portion already dried before feeding in Conveyor-2 (Big Conveyor)
ROOT CAUSE	W3- Two authorized personnel of CBMP items share in Conveyor-2.
PROCESS	
	W4-To cope-up the delivery requirement because this items have big volume quantity this month and run only in Conveyor 2 due to big sizes, why the Leader assign another authorized personnel for CBMP items to support.

	W1 - Only trial run checking are required in gluing				
CAUSE PROCESS/MATERIAL	W2 - Because there is on-line QA who check the items after feeding in conveyor 2.				

CORRECTIVE ACTION

Avoid two persons share in Conveyor-2, but to cope up the delivery schedule the 1st gluing will process manually by support operator (Authorized Personnel for CBMP items) and the Conveyor-2 operator process only 2nd gluing of CBMP boxes. (Under study of Production Leaders)

PIC:	Production	TARGET DATE:	If effective
------	------------	--------------	--------------