- A								
KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302			INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim					
				Control No.: 281 Date Issued: 20 08 27				
Customer	EPSON IJF		Attention To Mr. Gerald De Guzman					
Item Code	5150864-01		Department	Department PRODUCTION				
Item Description	scription INDIVIDUAL BOX			Date of Detection 20 08 27				
Job Order Number	WO-DRS-2	0-L-0068-94	Section Detected	Section Detected QA - IN LINE				
	ILLUSTRATION	OF THE PROBLEM	Minor Minor					
EPSON III			Lot Quantity (pcs.) Reject Quantity (pcs.) Reject Percentage 2.81% Nature of Defect: MISALIGN PRINT					
SLANT - NO GOOD EPSON III			Requirement: Print should not be in slant position and should not be cut by the die cut blade Actual:					
STRAIGHT - GOOD 精密機器につき取扱さ		精密機器につき取扱注意	The print is slanting and cut by diecut blade					
NO. OF OCCU	RRENCE	DISPOSITION	AREA OF OCC	CONTENT				
First		Hold	Slotter	Material				
Recurrence		Special Acceptance	EQOS	Vertical	Dimension			
No.:4		For Rework	Diecut	Others:	Appearance			
Date: 20 08 27		Reject / Disposal	Detaching		Process / Method			
Issued I	ру	Checked by	Approved t	ру	Received by			
Adrian Vergara QA-IE Staff		Ms. Noemi Cèpeda QA Supervispr	Mr. Rexe Alm QA Asst. Man	nario Mr.	Gerala De Guzman eagh Supervisor			
		I. INVESTIGAT	ION / ANALYSIS					
DIRECT CAUSE:	(Analyze the reas	son of occurrence, why it happened?)	INDIRECT CAUSE	E: (Analyze the reason of occurre	ence, why it leaked?)			
Why 1: Why 2: Why 3: Why 4: Why 5:	Why 2: Why 3: Why 4:			Why 1: Why 2: Why 3: Why 4: Why 5:				
Why 1:	Why 2:							
Why 2:				Why 2: Why 3:				
Why 3:								
Ď			Why 4:					
			Why 5:					
Why 1:			Why 1:					
<u>छ</u> भ्र Why 2:				Why 2:				
Dir Co			Why 3: PLS. SEE ATTACHED					
Why 4:	1-0	THURLED	Why 4:					
Why 5:			Why 5:					
, , , , , , , , , , , , , , , , , , ,			TYTHY O.					



KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

				FINAL CO	NCLUSION			
OCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
WARP MATERIALS					RANDOM OCCURRENCE			
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)					CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)			
A. Sorting Result	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				Actions to be done to eliminate recurrence Who / When			
	Location	n Total Stock	NG	Total Good				
RM	N/A				System	N/A		
WIP	NIA				Oystein	/ *		
FG	N/A							
B. Orientation						N/A		
Date	NIP	Time	N	/A	Design /			
Title		N/A			Tools	/ ~		
dees	N/A					The state of the s		
C. Reworking								
Rework Quantity		N/A	N/A			PLS. SEE ATTACKED		
Total Good		N/A	N/A			() () (ATTAGED)		
Rework Percenta	Rework Percentage (Good) N / A							
II. QA ROO	TCAUSE VERI	FICATION (To be filled out	by QA In-	charge)	Date Conduct	ed: 10 00 01 PIC: 11. VETO/01/01		
Identified Rootcause					Recommendation			
The moterial used are worp The paper weight jig used is not enough (The worp can develop in KPPI of the applied weigh jig for not worp is 1 piece conly)				not warp	Seperate the warp boards to not warp for separate Setup. Neight 196-should not be applied on the center of the boards also consider. The both ends.			

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)							
	Checked by	Date	Implemented?		Remarks		
1st Verification of Action	A. Yergara	2009 02	[/] Yes	[] No	Recommendation is implemented		
2nd Verification of Action	A. Vergava	20 09 03	[]Yes	[] No	C.A. #2 will not be pursue		
3rd Verification of Action	A. Vergara	20 09 09	[/] Yes	[] No	Additional weight Jigs is done		
Effectiveness of Action	A. Vergara	20 09 14	[] Yes	[] No	Recommendation is effective		

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE								
Status OUALITY ASSURANCE DEPARTMENT	Approved by:	Process Owner Acknowledgme	nt: (Receiving Section)					
Closed Still Oper Q Superv	V V	Line Leader	Department Head					
DATE AND	Date: 2011	Date: 21 01 11 Date	21001					

INVESTIGATION REPORT FOR MISALIGN PRINT OF EPSON IJP 5150864-01 INDIVIDUAL BOX

${f W1} ext{-}$ Eqos operator report to Leader in-charge regarding misalign print they encountered.

DIRECT CAUSE W2- Materials bump to the machine roller that caused misalign print.

W2- There's a random of warp materials.

W3 - Upon checking almost no paper weight Jig on the top of materials issued in Eqos, there is one paper weight jig but the position is useless.





INDIRECT CAUSE PROCESS/MATERIAL

PROCESS/MATERIAL

W1- Operator sort the affected of warp materials

W2- Because of random occurrence possible that they didn't trap all the affected of misalign print.

CORRECTIVE ACTION

Make additional Weight Jig

PIC: Concern Department TARGET DATE: On-going as of 200827

Orient the proper usage and study the effectivity of weight jig to warp materials.

700828

PIC: Concern Department TARGET DATE:

PREPARED BY:

GERALD DE GUZIVIAN PROD ASST. SUPERVISOR APPROVED BY:

- 2008/20 httpooli weena v. apalla sr. supervisor