1								
) No. 5 Ri	Ring Road LISP II, Brgy.	GE PHILIPPINE INC. La Mesa, Calamba City, Laguña	INVESTIGATION REPORT FORM (IRF)					
Telepho	one No. (049) 545-7166 . (049) 545-6302	to 69	Inhouse Detection	Cu	stomer Claim			
Little Venness			Control No.: 282	Date Issue	d: 20 09 02			
Customer	SFLI		Attention To Mr. Gerald De Guzman					
Item Code	839N		Department	Department PRODUCTION				
Item Description	CARTON BO)X	Date of Detection	20 09 01	,			
Job Order Nümber	WO-20-M-01	125-2	Section Detected QA - SCREENING					
	ILLUSTRATION (OF THE PROBLEM	Major	Mir	nor			
			Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
TID (S			300	84	28.00%			
		JLDS ECHNOLOGY em brand	Nature of Defect:					
CHNOLO			STITC	HED PRINT	CHANACTER			
m bra	na :		Requirement:					
			Stitch should not be fall on the text					
	(Actual:					
			The stitch coincide on the text					
NO. OF OCC	URRENCE	DISPOSITION	AREA OF OCCU	JRRENCE / ORIGIN	CONTENT			
First		Hold	Slotter	Gluing	Material			
Recurrence		Special Acceptance	EQOS	Vertical	Dimension			
No.:		For Rework	Diecut	Others:	Appearance			
Date:		Reject / Disposal	Detaching	STITCHING	Process / Method			
Issued	d by	Checked by	Approved by	y	Received by (Receiving Section)			
Adrian V QA-IE		QA Supervisor	Mr. Rexel Alma QA Asst. Manag	ari ()	Mr. Gerald De Guzman Head/ Supervisor			
QA-IE	Starr	NEW TOTAL STREET, AND THE PROPERTY OF THE PROP		iger -	/ Heady Subervisor			
DIRECTIONUS	25 (Analyze the resu	I. INVESTIGAT son of occurrence, why it happened?)	TION / ANALYSIS	: (Analyze the reason of occ	why it looked?)			
	SE. (Allalyze ule reac	300 of occurrence, why it happened ()		. (Allaryze me reason or occ	Sufferice, why it leaked :)			
Why 1:			Why 1:					
Why 2:		W/A	Why 2:	11/				
System / Training Mys 4:		//	Why 3:					
7.53			Why 4:					
Why 5:			Why 5:					
Why 1:			Why 1:					
. <u></u>			Why 3: PLS, SEE ATTACHE					
Why 2: Why 3: Why 4:	PLS. SE	E ATTACHED	Why 3:	2,500	18016			
Why 4:	•		Why 4:					
Why 5:			Why 5:					
Why 1:			Why 1:	- 1				
Process / Material Myh 3:		/	Why 2:	†				
Why 3:		N/A	Why 3:	PIA				
Why 4:	•		Why 4:	. /				
Δ. Why 5:			Why 5:					

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

ENDOS DE CONTROL DE CO	nementary and the state of the	caso programous concia tombio colo	TOTAL DESIGNATION AND ASSESSED.	MANUETTA VEGETA INTERNATIONALE	invalenti (SCII STORANIA)				
i de la companya di salah di s				FINAL CON	ICLUSION				
	OCCURF	RENCE ROOTCAUSE			OUTFLOW ROOTCAUSE				
NOT	I DEAL P	05/MOP 0	F Pr	ZINT	(SOOD BEFORE			
IMMEDIATE	ACTION: (Action to be	done to contain/ temporary	correct the pr	oblem found)	CORRECTIV	E ACTION: (Actions to be done to ensure that the problem will no	ot happen again)		
A. Sorting Result					Actions to be done to eliminate recurrence Who / When				
en a presupo establecto de contra sue a contra de la contra del la contra del la contra del la contra del la contra de la contra de la contra del	Location	Total Stock	NG	Total Good					
RM	N/A				System	K) /6			
WIP	NIA				System	NA			
FG	N/A						1		
B. Orientation									
Date	N/A	Time	N	/A	Design /	PLS. SEE ATTACHED			
Title		N/A							
ees	3 T	N/A							
C. Reworking									
Rework Quantity		N/A			Process	N/A			
Total Good		NIF	NIA			N/A			
Rework Percenta	age (Good)	NII	A						
II. QA RO	OTCAUSE VERIFIC	ATION (To be filled ou	ıt by QA In	-charge)	Date Conducted	: 100904 PIC: A. Vergara			
		tified Rootcause			Recommendation				
~ The logo edge of the reach 23m	panel is elma	because it's only white the	distance stitches	from the s can	"The stitching operator should avoid the togo of the item." Indicate in the drawing "Avoid logo during stitching Process": Propose to cus tomer to move the logo by 12mm				
		III. CORREC	TIVE ACTI	ON VERIFICATI	ON (To be filled	out by QA In-charge)			

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)							
	Checked by	Date	Implemented?		Remarks		
1st Verification of Action	A. Vergara	2009 10	[/] Yes	[] No	Recommendation is implemented (Except for change design)		
2nd Verification of Action	A Vergara	20 09 11	[]Yes	[/]No	change design proposal with not pursue same w/ rejection enterior		
3rd Verification of Action			[]Yes	[] No			
Effectiveness of Action	A. Vergara	2009 15	[/] Yes	[]No	Transfer in SFLI		

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV: CLOSURE									
S	QUALITY	ASSURANCE	DEPARTMENT	Approved by:		Process Owner Acknowled	gment: (Receiving Section)		
Clo	sed TRANSF	er in spu	J _Q A ₃	Pau GASS	MMM VA	Line Leader	Department Head		
Re-	sst IRF		Date: // 2	10/// Date: K	11 16	Date: 21 01 11	Date: 21 01 11		
	DATE AND	ma -	,				U		


INVESTIGATION REPORT FOR STITCHED PRINT CHARACTER FOR SUPERFLEX 839N CARTON BOX

DIRECT CAUSE

W1- The distance of print from the edge of box is 22mm only vs. 40mm glue tab.

DESIGN/TOOLING

W2- The location of print is prone to stitched, or not in the ideal position.



W1- No instruction in the drawing that stitch should not be hit on the print character.

INDIRECT CAUSE DESIGN/TOOLING

W2- This occurrence is normal and good before.

W3- First time to reject this occurrence.

CORRECTIVE ACTION

Move the print dimension from 22mm to 40mm for sure that the print didn't hit by stitch.

PIC:

SALES & DESIGN

TARGET DATE:

If ever the print movement did not approved, provide rejection criteria and put instruction in the drawing regarding this issue.

PIC:

QA & DESIGN

TARGET DATE:

PREPARED BY:

PROD ASST. SUPERVISOR

APPROVED BY: