KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

				FINAL CO	NCLUSION			
hieron k	OCCURRE	NCE ROOTCAUSE			OUTFLOW ROOTCAUSE			
TIC DUE	STAIN.	THE ITEM	THE AWD IT	BASE OF CHUSED	-ND OF FITTON OR THE NAME OF THE			
IMMEDIATE	ACTION: (Action to be do	one to contain/ temporary	correct the pr	oblem found)				
A. Sorting Result						Actions to be done to eliminate recurrence	Who / When	
	Location	Total Stock	NG	Total Good				
RM	N/A					N/		
WIP	N/A				System	N/A		
FG	N/A							
B. Orientation								
Date	N/A	Time	N/	'A	Design /	.,,,		
Title	NIA			Tools	P/A			
Attendees	N/A							
C Jorking								
Rework Quantity	N/I	N/A						
Total Good	•	N/A				PLS. SEE ATTACHED		
Rework Percentage (Good)		NIA						
II. QA ROC	OTCAUSE VERIFICATI	ON (To be filled out	t by QA In-	charge)	Date Conducted	1: 20 01 05 PIC: A. Vergara		
Identified Rootcause					Recommendation			
> Glue con designs o	tamination fr f the item h	om Jig beca as a hole	ause t on th	he le center	> Fabrica glue cont	te jig for dunnage set to pr tamination	event	

	Checked by	Date	Implemented?		Remarks	
1st Verification of Action	A. Vergara	21 01 05	[/] Yes	[] No	Recommendation is implemented	
2nd Verification of Action	A. Vergara	21 01 08	[]Yes	[] No	C.A. will not be pursue	
3rd Verification of Action			[]Yes	[] No		
Effectiveness of Action	A. Vergara	21 63 13	[/Yes	[] No	Recommendation is effective	

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE											
Status: Remarks: DEDADT	Approved by:	Process Owner Acknowledgment: (Receiving Section)									
SILVE QUALITY ASSURANCE DEFAIL	Mal QA Assimanage	Line Leader Department Head									
	Date: 210414 Date: 210414 D	Date: 210414 Date: 210414									


DATE AND SIGNATURE 91 04 14

INVESTIGATION REPORT FOR GLUE STAIN OF NIDEC SUBIC DUNNAGE SET TOP AND BOTTOM

DIRECT CAUSE PROCESS/MATERIAL $\overline{W1}$ - Possible that the glue stain came from the jig that they used during assembly.

W2- During application of glue using paint roller, the roller with glue touched the base of jig due to hole of the item and it caused glue stain.





GLUE LEAK IN THE BASE OF JIG **THAT CAUSED GLUE STAIN**

(OUTFLOW) PROCESS/MATERIAL

INDIRECT CAUSE W1- Because the glue stain is unavoidable due to the design and process of the item, and no rejection criteria yet because the item is IPD the operator think that the small amount of glue stain is acceptable.

PRODUCTION CORRECTIVE ACTION

Create rejection criteria that applicable base on the items design and process.

PIC:

SALES, QA & PRODUCTION

TARGET DATE:

DISCUSS TO 4PM MEETING

PREPARED BY:

APPROVED BY: