INVESTIGATION REPORT FOR MISALIGNED CUT (516018500 PANEL A-LIONEL PG EAL) W1: Misaligned cut occured due to wrong setting. W2: Adjustment of settings due to printing. INDIRECT CAUSE METHOD Settings not proper check before running

PRODUCTION ACTION PLAN

IMMEDIATE ACTION:

/ PROCESS

Proper setting of side guide.

PREVENTIVE ACTION:

Striclty following of the printing guide.

Prepared by: Reviewed by:

PRODUCTION IE TEAM Sir Marco Pesa

Noemi Cepeda **PRODUCTION SUPERVISOR**