485					
No. 5 Rir	MEPACKAGE PHILIPPINE INC. ng Road LISP II, Brgy, La Mesa, Calamba City, Laguna	INVESTIGATION REPORT FORM (IRF) Inhouse Detection Customer Claim Control No.: 263 Date Issued: 20 08 06			
Telephor	ne No. (049) 545-7166 to 69 (049) 545-6302				
Customer	NIDEC SUBIC	Attention To Mr. Gerald De Guzman			
Item Code	L00086478	Department PRODUCTION			
Item Description	FLEXWAVE C BOX	Date of Detection 20 08 04			
Job Order Number	WO-SO-IPD-1220-1	Section Detected	QA - IN LINE		
	ILLUSTRATION OF THE PROBLEM	Major	Minor		
		Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage	
BOOK I		Nature of Defect:		<u> </u>	
	Native		MISALIGN PRINT		
WID BENGGERAL FI	EXUAVE SUMXYY	Requirement:			
)			he character should not be slan	ting	
	Afelese Afelese	Actual:	The printed characters are slant	ed	
NO, OF OCCU	RRENCE DISPOSITION	AREA OF OCCU	JRRENCE / ORIGIN	CONTENT	
First	Hold	Slotter	Gluing	Material	
Recurrence	Special Acceptance	EQOS	Vertical	Dimension	
No.:	For Rework	Diecut	Others;	Appearance	
Date:	Reject / Disposal	Detaching		Process / Method	
Issued b	Y Checked by	Approved by	,	Received by (Receiving Section)	
Adrian Verg		Mr. Rexel Alma QA Asst. Mana	ario Mr. 9	erald De Guzmah ead/ Supervisor	
DIRECT CAUSE:	I. INVESTIGAT (Analyze the reason of occurrence, why it happened?)	ION / ANALYSIS INDIRECT CAUSE:	(Analyze the reason of occurre	nce, why it leaked?)	
Why 1:		Why 1:			
Why 2:		Why 2:			
Why 2: Why 3: Why 4:	N/A	Why 3:	NA		
		Why 4:			
Why 5:		Why 5:			
Why 1:		Why 1:		4.5	
Segue of the seguence of the s	N/A	Why 2: Why 3:			
Why 3:	/#				
		Why 4;			
Why 5:		Why 5:			
Why 1:		Why 1:			
Why 2: Why 3: Why 4:	Dic c	Why 2:			
Why 3:	PLS. SEE ATTACHED	Why 3:	S. SEE ATT	TACHED	
	100 m	Why 4:			
Why 5:		Why 5:			

DATE AND

SIGNATURE

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy, La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 545-6302								
					FINAL CO	NCLUSION				
OCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE					
- TRANSFER OF PROCESS FROM SIZOD TO ETTRINA. - DISCREPANCY IN DRAWING US. CYNEZ.					- EDDS OPERATOR DIDN'T NOTICE THE MISALIGN PRINT BECAUSE THE ITEMS ARE NOT YET DIE-CUTTED.					
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)				CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)						
A. Sorting Resul	t						A A SCHOOL STREET	pe done to eliminate recurrence	Who / Whe	
	Lo	cation	Total Stoc	k NG	Total Good		N/A			
RM	NI	A								
WIP	N	Α	and the second s			System				
FG	N	/A								
B. Orientation										
Date	N	11	Time	NIA		Design /	N/A			
Title			NIA			Tools				
Ittendees			N/A							
C. Reworking										
Rework Quantit	ty		NIA					011 (
Total Good			NIX)		Process	PLS. SEE ATTACHED			
Rework Percen	tage (Good)	1/1							
II. QA RC	OTCAUSE	VERIFICATION	ON (To be filled	out by QA In-	charge)	Date Condu	cted: 20 0g	10 PIC: A-Verogra		
			d Rootcause			Recommendation				
> The prin item has the printi	high is	in oblic tacking hine	que pasition height in	on because the feedin	se the ng unit of	> Recluce > Mount monitor oblique	ing of or	, height(came w/ 1012) kayoke marks on the m ting movement for vertica	flar to 1 Position 9	
<u></u>				RECTIVE ACTIO	N VERIFICATI	ON (To be fil	led out by QA	In-charge)		
		Ghe	cked by	Date	Implen	ented?		Remarks		
1st Verification	of Action	A.Verco	gara	20 10 17	[/Yes	1 1 No Recommendation is implemented				
2nd Verification	of Action				[]Yes	[] No				
3rd Verification	of Action				[]Yes	[] No				
Effectiveness	of Action	A. Vergara 21 09 16 [AYes		[] No	No Recommendation is effective					
Note: If no sam deliveries or 3rd	e defects / j d verification		not yet iinpiein	erkeu, mvestiga	IV. CLO	SURE	red effective / c ed to the affecte	closed. If the same problem occurs within ed department to provide new improvement	nt action.	
Close I	PALITY /	ASSURAI	ICE DEPA	ham	Approv	— AH	monut	Process Owner Acknowledgment: (Red	celving Section)	

U D9 16

09 16

Date:

21 09 16

Department Head

21 09 16

Date:

21 09 16


Date:

INVESTIGATION REPORT FOR MISALIGN PRINT OF NIDEC SUBIC L00086478 FLEXWAVE C BOX

DIRECT CAUSE PROCESS/MATERIAL

W1- Item under adjustment stage because this is IPD and from Diecut S1700 during sample making, this item transfer in Eterna why the Eqos operator take an hour to setup the layout of this item.

W2- We found discrepancy in Drawing vs. Cyrel even the Nidec logo is within center line requirement, but there is excess 5mm print in lower flap.





39mm lower

DESCRIPANCY IN DRAWING vs. CYREL THE NIDEC LOGO IS ALMOST CENTER LINE BUT THERE IS EXCESS 5mm PRINT IN LOWER FLAP

PROCESS/MATERIAL

W1- Operator proceed to mass production.

INDIRECT CAUSE W2- Trial run approved by QA.

W3- Eqos operator didn't notice the misalign print because the items are not yet die-cutted.

CORRECTIVE ACTION

Coord	inate this problem in Sales in-charge acc	ording the problem in d	liscrepancy between Drawing vs. Cyrel.
PIC:	PRODUCTION	TARGET DATE:	200811

TARGET DATE:

Put pokayoke mark as allignment reference for print in both mylar of Black & Green cyrel.

PREPARED BY:

PIC:

GERALD DE GUZMAN PROD ASST. SUPERVISOR

PRODUCTION

APPROVED BY:

SR. SUPERVISOR

Next running

DOOR