SIGNATURE_

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna

INVESTIGATION REPORT FORM (IRF)

Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302								
FINAL CONCLUSION								
OCCURRENCE ROOTCAUSE					OUTFLOW ROOTCAUSE			
- (OHOT DUT) STICK IN THE CITIZE			- OCCUPS AT PHE END POPUTION OF MASS PRODUCTION					
IMMEDIA	TE ACTION: (A	ction to be done to contain/ tempor	ary correct the prob	olem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)			
A. Sorting Res	ult				Actions to be done to eliminate recurrence Who / When			
	Loc	ation Total Stock	NG	Total Good				
RM	N/	А			System	N/A		
WIP	N/	A			Cycloni	//		
FG	N/	A						
B. Orientation								
Date	21 04 13	Time	16-33-16	0:39	Design /	14/4		
Title	DRIENTATION	regarding scum of hid	ec-subic VR-D) Box	Tools	-/A		
dees	EQUS OF	PERATORS						
C. Reworking								
Rework Quar	ntity	NIA	NIA		Process	PLS. SEE ATTACHED		
Total Good		N/A				(or) or minery		
Rework Perce	entage (Good)	N/A						
II. QA I	ROOTCAUSE	/ERIFICATION (To be filled	out by QA In-c	harge)	Date Conduc	Date Conducted: 1 04 00 PIC: A VCIQAVA		
		Identified Rootcause			Recommendation			
The ink was contaminated by dirt. Since flexo plate was contaminated by adhosive. There was an adhosive on the material surface								
		III. CORR	ECTIVE ACTIO	N VERIFICATI	ON (To be fill	ed out by QA In-charge)		
		Checked by	Date	Implem	ented?	Remarks		
1st Verification of Action		A. Vergara	21 04 13	[A Yes	[] No	c.A. is implemented		
2nd Verification of Action				[]Yes	[] No			
3rd Verification of Action				[]Yes	[] No	No		
Effectiveness of Action		A. Vergara	21 10 18	[Y es	[] No	O.A. is effective		
						*		

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE						
THOUGHT ASSUBITION DEDADT	Approved by:	Process Owner Acknowledgment: (Receiving Section)				
Cosed Control DEPART	A Supervisor QA Asst Manager	IRISH MAY L. ESTAREJA Line Leader Department Head				
DATE AND	Date: 21 10 18 Date: 21 10 18	Date: 21 10 18 Date: 21 10 18				

INVESTIGATION REPORT FOR SCUM OF NIDEC SUBIC VR-D BOX

	W1-	There is adhesive (Double sided tape) stick in the material surface.			
DIRECT CAUSE PROCESS/MATERIAL	W2- The adhesive stick in the cyrel during mass production.				
	W3 - Ink did not	penetrate in the portion of cyrel have adhesive that caused of scum.			

(0	INDIRECT CAUSE	W1 - Operator and QA Patrol did not notice the scum during sampling.					
	(OUTFLOW) PROCESS/MATERIAL	W2 - Possible the scum occurs at the end portion of mass production.					

PRODUCTION CORRECTIVE ACTION

Alert the Eqos operator that upon detection of scum immediately clean the cyrel before proceed to mass production.


PIC: PRODUCTION TARGET DATE: 210408

PREPARED BY:

GÉRALD DE GUZMAN
PROD ASST. SUPERVISOR

APPROVED BY:

WEENAV. APALLA SR. SUPERVISOR



		MINUTES C	OF THE MEETING		
Date: 2104/3	Time Start:	1633H	Time /439H	Venue:	EGOS ANGA
ATTENDEES: Name	Section	Sign	Name	Section	Sign
Marxin Pampallakin Henry CLAVE TOLITE HERD	7Q0(N	Alla Inv			
PEDILO CHAPET	Eloos	PAGE			
AGENDA:			ATION REGARDING IDEC SUBIC VR-D B		
MINUTES:					page 1 of 1
ROOTCAUSE:					
			material surface, the adhesive we adhesive that caused of scu		during mass productio
RECTIVE ACTION:					
	of scum imme	ediately clean the c	yrel before proceed to mass p	roduction.	
> Make sure the cy	rel totally dri	ed before resume t	to mass production.		
		HERATANA Departament			
FOLLOW UP MEETING:			Same of the second of the second		
(date & time)					
for KPPI fill up only					
Prepared by:		Reviewed by:	^	loted by:	
GERANO DE GUZMAN					