2071

KANEPACKAGE PHILIPPINE INC.			IN	INVESTIGATION REPORT FORM (IRF)			
Telephor	ng Road LISP II, Brgy. L ne No. (049) 545-7166 to (049) 545-6302	.a Mesa, Calamba City, Laguna o 69	Control	Inhouse Detection Customer Claim Control No.: 437 Date Issued: 21 06 24			
Customer	CANON		Attentio	Attention To Mr. Gerald De Guzman			
Item Code	RX1-5115-000	0	Department PRODUCTION				
Item Description	Z10 ACC BOX			Date of Detection 21 06 23			
Job Order Number	JO-F-21-188-	5	Section Detected SCREENING				
ILLUSTRATION OF THE PROBLEM			Major Minor				
			Lo	ot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage	
	13/52 13			4,100	104	2.53%	
	Company of the last		Nature	of Defect:			
					PEEL OFF		
					122011		
			Requir	ement:			
					No peel off on the item		
			Actual				
					W/ peel off on the smooth sur	face	
NO. OF OCC	URRENCE	DISPOSITION		AREA OF OC	CURRENCE / ORIGIN	CONTENT	
First		Hold		Slotter	Gluing	Material	
Recurrence		Special Acceptance		EQOS	Vertical	Dimension	
No.: 4		For Rework		Diecut	Others:	Appearance	
Date: 21 06 2	23	Reject / Disposal		Detaching		Process / Method	
Issued	l by	Checked by		Approved	i by	Received by (Receiving Section)	
M	m	/hda		Ar	0/	est.	
Adrian Vergara Mr. Roderick Ramos				Mr. Rexe	marle M	Gerald De Guzman	
QA-IE		QA Supervisor 21002	7	QA Asst. Ma	anager	Head/ Supervisor	
entropy (144 - Archelt		I. INVESTIGA	AT A SECURE AND A SECURE ASSESSMENT	NALYSIS			
DIRECT CAUS	E: (Analyze the reas	on of occurrence, why it happened?)		INDIRECT CAU	SE: (Analyze the reason of occu	urrence, why it leaked?)	
Why 1:			Why 1:		44		
Why 2:			Why 2:	4	,		
Why 3:			Why 3:	Why 3: 15/15_			
Why 2: Why 4:			Why 4:				
Why 5:			Why 5:				
Why 1:			Why 1:		1		
Why 2: Why 3: Why 4:			Why 2:				
			Why 3:		V/K		
			Why 4:				
Why 5:			Why 5:				
Why 1:			Why 1:		a = 00/87()=		
Myy 2: Why 3: Why 4:	<i>Q</i> 1 - 4	CTE GTAMED	Why 2:	Ore	, SEE ATTA	UED	
Why 3:	125-	SEE ATTAGLED	Why 3:	1/25	. ,0=		
Why 4:			Why 4:				
ک Why 5:			Why 5:				

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna

INVESTIGATION REPORT FORM (IRF)

	Telephone No. (Fax No. (049) 5	(049) 545-7166 t 45-6302	co 69					` /
4.4					FINAL CON	CLUSION		No. 2016
	О	CCURRENCE	ROOTCAUSE	E			OUTFLOW ROOTCAUSE	
_ '	Brok	el) r	39CKW	C TX	PE		THIN DIMENSION OF PER	LOFF
IMMEDIA	TE ACTION: (Action to be done	to contain/ tempora	ary correct the prob	lem found)	CORREC	TIVE ACTION: (Actions to be done to ensure that the problem will not ha	ppen again)
A. Sorting Resu	ult						Actions to be done to eliminate recurrence	Who / When
Kanangan, ang	Loca	ation	Total Stock	NG	Total Good			
RM	N/	A		Ext. VIII		Custom	N/A	- 4
WIP	N/					System		
FG	N/							
B. Orientation								
Date	N	/A	Time	N	'A	Design /	V/4	
Title			N/A			Tools	1/25	
Attendees			N/A					
C. Reworking								
Rework Quan	tity	N/A			Process	PLS. SEE ATTAGED		
Total Good			N/A			Flocess	(D) CE KVINGTON	
Rework Perce	entage (Good)		N	1/A				
II. QA F	ROOTCAUSE \	/ERIFICATIO	N (To be filled	out by QA In-c	harge)	Date Conduc	ted: 21 No 25 PIC: A. Vergara	_
		and the second	Rootcause				Recommendation	
the app	lied bac	king ta		ough become thin.		ON (To be fil	led out by QA In-charge)	45 X700.5
		Chec	cked by	Date	Market Advanced	nented?	Remarks	
1st Verificati	ion of Action	A. Verg	ara	21 06 29	[\text{\tinit}\\ \text{\ti}}\\tittt{\text{\texi}\text{\text{\texi}\text{\text{\text{\text{\texi}\text{\text{\texi}\text{\texi{\texi{\texi{\texi{\texi}\text{\texi}\texitt{\texi}\tilint{\texit{\texi{\texi}\texit{\texi	[] No	C.A. is offective	
2nd Verificat	tion of Action				[]Yes	[] No		
3rd Verificat	ion of Action				[]Yes	[] No		
Effectiveness of Action A.Vergara		21 09 28	Yes	[] No	C.A is effective			
							ored effective / closed. If the same problem occurs within 5 co and to the affected department to provide new improvement ac	
	14.				IV. CLC	SURE		
Status:		Remarks:		100	Appro	ved by:	Process Owner Acknowledgment: (Receiving	ing Section)
Closed				Ma	16	CÂKM	WONTO IRISH MAY L. ESTAREJA	
Still Open				/	pervisor	JA A	tt. Manager Line Leader Departme	-1
Re-Issue IRF				Date: 11 D	9 28	Date: ZI O	908 Date: 21 0908 Date: 71 0	7 18

INVESTIGATION REPORT FOR PEEL OFF OF CBMP RX1-5115-000 Z10 ACC BOX

W1- Due to operator encountered Uncut during mass production.

DIRECT CAUSE PROCESS/MATERIAL

W2- Due to lack of backing tape caused by decrease in the pressure.

W3- Due to the pressure was set to 1.5 tons instead of 2 tons to avoid bursting and easy detach of scrap in delivery area.

K KANED	COLACIE PROLIFERING INC.
COMMON AND	SE CHARLES TO SECURE
CHIEF ACTIVITIES	THE STREET PRODUCTION OF THE PARTY OF
78 (18 fee fee)	and the same particular and
Laures	20-00-5
Edit Francisco	EX. 505
54700	A Page
Contraction to	Park Street Street Street Street Street Street
Martin Martin Co.	1802
FREE NAME	Macre 7410
The Print	Marine County Control of
	THE HOUSE
SP1044	12
2.00	196
-	test than
CONTRACTOR STATES	1
F STATE OF	two tra
Minima rin ne ya Neglinsa Yali	tane than
	1 1850 1850
production of the	County and the second
to Come Section	and the same of th
1 Cally per tires.	L
2 500 y 160 Fe	Bay (lean in
A det prompte	D44 315
a borden	Serie Hosser
A CR Columbia	100/2011
the second second second	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.
i mari	SHOP THE RESIDENCE AND ADDRESS OF THE PARTY
	INCO PRINCEL
S. Landon	Personal Residence and Control Residence and
PRODUCTION OF	and the second publishment for
SERVICE STATE OF THE PARTY NAMED IN COLUMN TWO IS NOT THE PARTY NAMED IN COLUMN TWO I	**************************************

Operator Call 6	LEX INDIAK
Job Order No. 1	21-84-5
Customer	ceno
Item Description	RX15115
Quantity	1025
Condition Sheet	
Actual Machine Speed	1900
Actual Machine Press ce	2 - 15
Sheet Size	1130x746
Vaterial	PSP

HEET		Bickey Bickey		
tje Stati	e Fireh	Marpine Britanism (Disprises) Cities		
Onor	javo	SET UP OVE TO SEED.		
3 —		Whit coash Whit bettings that The core dear experiences and the core dear experiences and the core of the core of the core of the core of the core of t		

MACHINE RATIO THAT SHOWS
PUT BACKING TAPE DUE TO
UNCUT DURING MASS
PRODUCTION



DELIVERY ERROR DUE TO EASY DETACH

INDIRECT
CAUSE
(OUTFLOW)
PROCESS/MATERIAL

W1- Diecut and Detaching operator didn't notice the peel off during sampling since it was very thin with 3x30mm dimension only.

PRODUCTION CORRECTIVE ACTION

> Revision of Eterna Diecut - Standard Machine Setting.

PIC: PRODUCTION

TARGET DATE:

210629

KANEPACKAGE PHILIPPINE INC.

ETERNA DIECUT - STANDARD MACHINE SETTING						
FLUTE TYPE	without	AUTO-STRIPPER	WITH AUTO-STRIPPER			
PLOIE 11PE	MACHINE SPEED (S/H)	MACHINE PRESSURE (TONS)	MACHINE SPEED (S/H)	MACHINE PRESSURE (TONS)		
А	3,000 - 4,500	1-2	2,000-4,000	1-2		
В	3,000 - 4,500	1-2	2,000-4,000	1-2		
С	3,000 - 4,500	1-2	2,000-4,000	1-2		
CB	1,800-3,000	1-4	1,800-3,000	1-4		
E	1,800-3,000	1-2	1,800-3,000	1-2		

NOTE: For Die blade with Eferan Layout to avoid bursting do not use pressure below 1.5 tons to avoid uncut.

Prepared By:

Checked By:

Approved By:

Lei Ann Marie Aviles Prod. IE Staff Weena Apalla Sr. Prod. Superviso

Jennifer Gallos Asst. Vice President

PREPARED BY:

LEI ANN MARIE AVILES
PROD IE STAFF

APPROVED BY:

HUNCOUN 21002 VEENAV. APALLA