No. 5 Teleph		E PHILIPPINE INC. a Mesa, Calamba City, Laguna o 69	INVESTIGATION REPORT FORM (IRF) Inhouse Detection						
Customer	CANON		Attenti	on To	Mr. Gerald De Guzman				
Item Code	RX1-5781-000)	Depar	tment	PRODUCTION				
Item Description	Z10 CARTON		Date o	f Detection	21 07 123	07 123			
Job Order Number				n Detected	QA - IN LINE	QA - IN LINE			
	ILLUSTRATION O	F THE PROBLEM		Major	Mino	or			
			L	ot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage			
			and an area of the same	950	46	4.84%			
			Nature	Nature of Defect:					
			A11176A20A		DENT				
				Requirement:					
			60mm length only						
				Actual:					
			150mm above length						
NO. OF OC	CURRENCE	DISPOSITION		AREA OF OCC	CURRENCE / ORIGIN	CONTENT			
First		Hold		Slotter	Gluing	Material Material			
Recurrence		Special Acceptance		EQOS	Vertical	Dimension			
No.:		For Rework		Diecut	Others:	Appearance			
Date:		Reject / Disposal		Detaching		Process / Method			
Issu	Issued by Checked by			Approved by Received by (Receiving Section)					
Adrian Vergara QA-IE Staff Mr. Roderick Ramos QA Supervisor				Mr. Rexel Amario QA Asst. Manager Mr. Gerald De Guzman Headt Supervisor					
		I. INVESTIGA	TION / A	MANAGAM MENANGAN	h) in a second				
DIRECT CAU	JSE: (Analyze the reas	on of occurrence, why it happened?)		INDIRECT CAUS	SE: (Analyze the reason of occu	urrence, why it leaked?)			
Why 1:			Why 1:						
Why 2:			Why 2:		/				
Why 3:	r/A	L	Why 3:	Why 3:					
Why 2: Why 4:				Why 4:					
Why 5:			Why 5						
Why 1:			Why 1						
. <u></u>	8			Why 2: Why 3: Why 4:					
Why 3:	P	P/K							
Why 2: Why 4:									
Why 5:			Why 5						
Why 1:			Why 1						
Why 2:		Why 2:							
Why 2: Why 3: PLS. SEE ***TACHED Why 4:				Why 3: PLS. SEE ATTACHED					
Why 4:			Why 4						
Why 5:			Why 5	Why 5:					

DATE AND SIGNATURE

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 5	45-6302											
FINAL CONCLUSION													
	C	CCURRENCE ROOT	CAUSE				(DUTFLOW ROOTCAUSE					
TO CUTTING BLADE.						NOT 50 VIENBLE.							
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)					CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)								
A. Sorting Result							Actions to be done to eliminate recurrence Who / When						
350000 100000 00.000000000000000000000000	Loc	ation Total	Total Stock	NG	Total Good								
RM	N	/A				System	k2/,						
WIP	N	/A				Oystem	N/A			-			
FG		/A											
B. Orientation									54 1 kr				
Date	N	IA Ti	Time N/A		A	Design /	P/A						
Title		N	Alu			Tools	177						
Attendees		N,	'A										
C. Reworking													
Rework Quant	ity)	N/A			Process	PLS. SEE ATTACHED						
Total Good	otal Good		N/A							4 7 -			
	Rework Percentage (Good)		THE POST OF THE PARTY OF	/A			0.10000						
							Date Conducted: 11 D7 I5 PIC: A. VEXDATA						
\t\	- C	Identified Rootcau				Recommendation							
> The scrap from the slot was left in die cut platform since there were no nickmark on the affected cutting blade													
		III. C	ORREC	CTIVE ACTIO	N VERIFICATI	ON (To be fil	led out by QA In-	charge)		1.00			
		Checked by		Date	Implem	ented?		Remarks					
1st Verification of Action		A. Vergara	Vergara 2107 15 1,24es		[]Yes	[]No C.A. is i		implemented					
2nd Verification of Action					[]Yes	[] No							
3rd Verification of Action					[] Yes	[] No							
Effectiveness of Action		A. Vergara 21 09 29 1240			[]Yes	[] No	C.A. is effective						
Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.													
					IV. CLC	SURE							
Status:		Remarks:		1) Approv	ved by:		Process Owner Acknowled	gment: (Receiv	ving Section)			
SinQUAL	TY ASSU	RANCE DEPA	RTM	NT CA SU	pervisor	QA Assa Manager		IRISH MAY L. ESTAREJA Line Leader	Departm	ent Head			
Renesue IRF					9 29	Date: 21 0	919	ate: 21 09 29	Date: 21 09	19			


INVESTIGATION REPORT FOR DENT OF CBMP RX1-5781-000 Z10 CARTON

W1- There is scrap from upper flap slot left in the stripping blade that caused dent in the item.

DIRECT CAUSE PROCESS/MATERIAL

W2- The scrap of slot in the upper flap got easily detached during auto stripping process.

W3- There is discrepancy between drawing vs. actual blade which is the upper flap slot portion have cutting blade.



NO CUTTING BLADE IN THE SLOT PORTION
BOTH FLAP



LOWER FLAP IS GOOD



UPPER FLAP HAVE CUTTING BLADE

INDIRECT CAUSE (OUTFLOW)

(001112010)

W1- Operator more pocus on the Uncut and Peel Off problem since this item is under go auto stripping in Eterna and they didn't notice the dent because it is not so visible.

PRODUCTION CORRECTIVE ACTION

Put nick mark in the cutting blade on upper flap slot to eliminate easy detach of slot scarp.

PIC:

PRODUCTION

TARGET DATE:

210715 (DONE)

PREPARED BY:

GERALD DE GUZIMAN PROD ASST. SUPERVISOR

APPROVED BY:

WEENA V. APALLA SR. SUPERVISOR