KAN	EPACKAG	E PHILIPPINE INC.	INVESTIGATION REPORT FORM (IRF)					
Telephone	e No. (049) 545-7166 to	a Mesa, Calamba City, Laguna 69	Inhouse Detection	omer Claim				
Fax No. (049) 545-6302		Control No.: 473	Date Issued: 21 10 13				
Customer	KOWA EMOR	1	Attention To	Mr. Gerald De Guzman				
tem Code	HP01D2000		Department	PRODUCTION				
tem Description	CARTON BOX	(Date of Detection 21 10 12					
Job Order Number	JO21-M-01629	9-8	Section Detected QA - SCREENING					
	ILLUSTRATION OF	THE PROBLEM	Major	Mino				
		D2000	Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage 1.67%			
			Nature of Defect: DENT					
			Requirement:					
			No dent mark on the surface of the box					
			Actual:		2			
			W/ Dent on the body of the box					
NO. OF OCCU	JRRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN CONTENT					
First		Hold	Slotter Gluing Material					
Recurrence		Special Acceptance	EQOS	Vertical	Dimension			
No.:		For Rework	Diecut	Others:	Appearance			
Date:		Reject / Disposal	Detaching		Process / Method			
	Issued by Checked by			by	Received by (Receiving Section)			
Adrian Vergara QA-IE Staff Mr. Roderick Ramos QA Supervisor			Mr. Rexe Almario QA Asst. Manager Mr. Gerald De Guzman Head Supervisor					
		<u> 1908), K. Maria da manda da </u>	TION / ANALYSIS		No. 11 Les 10			
DIRECT CAUS	E: (Analyze the reas	on of occurrence, why it happened?)	INDIRECT CAUS	SE: (Analyze the reason of occu	irrence, why it leaked?)			
Why 1: Why 2: Why 3: Why 4: Why 5:	٨)/A	Why 1: Why 2: Why 3: Why 4: Why 5:					
Why 1: Why 2: Why 3: Why 4:	۲	/ <u>A</u>	Why 1: Why 2: Why 3: Why 4:					
Why 5: Why 1: Why 2: Why 3: Why 4: Why 5:	PLS.	SEE ATTACHED	Why 5: Why 1: Why 2: Why 3: Why 4: Why 5:	PLS. SEE ATTACHED				

R

DATE AND SIGNATURE

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LTSP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302


INVESTIGATION REPORT FORM (IRF)

	Fax No. (049) 5	10 0002							See State of the Land	20/45/2019	国海经济经济
		OCUPPENCE D	OCTONUCE		FINAL CON	ICLUSION		OUTEL OW BO	OOTCAUSE		
	U	CCURRENCE RO	JOTCAUSE					OUTFLOW RO			
-THE STRIPPING BLADE IS POINTED							- DENT DID NOT NOTICE IMMEDIMEN				
AND	LITTLE	BIN IN	UPWAR	D POS							
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)						CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)					
A. Sorting Result						Actions to be done to eliminate recurrence Who / When					
100000000000000000000000000000000000000	Loca	ation T	otal Stock	NG	Total Good						
RM	N/	A				System	P/A				
WIP	N/	A				Cyclom					
FG	N,	A A									
B. Orientation							21-11-1	N/		- 4	
Date	N	10	Time N/A		A	Design / Tools	P/A				
Title			NIA								
Attendees			N/A							\ \	
C. Reworking								0			
Rework Quan	tity			7/U		Process	PLS. SEE ATTACHED				
Total Good				VA							
REPRESENTATION OF THE PROPERTY	ework Percentage (Good)								- 12 Varia		
II. QA R	OOTCAUSE	ERIFICATION (T	Balanda Bar	ut by QA In-	charge)	Date Conducted: 21 15 14 PIC: A. Veropio					
		Identified Roo				Recommendation					
> the stripper blade on the female stripper has a sharp corner a slanted										CO TRAINS	
		Checked					led out by QA	n-cnarge)	Remarks		
		Criecket	iby	Date	implen	nented?					
1st Verificati	on of Action	A. Vergara		21 10 18	[/] Yes	[]No C.A. is implemented					
2nd Verification of Action				[]Yes	[] No						
3rd Verificati	3rd Verification of Action				[]Yes	[]No					
Effectiveness of Action A. Vergara		1	21 11 04	11 04 [/] Yes		c.A. is effective					
Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.											
ueliveries or	oru veriilcatioi	ı oı action stili not	yet impleme	meu, mvestig	Necessary of the second		eu to the allecte	ы иеранивен в	ο provide new imp	orovernent i	action.
CL-L		Domeste			IV. CLC			Process Ou	or Agknowleds	ont: /Dessi:	ing Soction
Status:		Remarks:		Λ	Appro	ved by:		OMSA!	er Acknowledgm	ent. (Recell	ving Section)
QUALITY ASSURANCE DEPARTMENT OF A Supervisor					QA Asst Manager IRISH MAY L. ESTAREJA Line Leader Department Head						
										6: 2LH	74

INVESTIGATION REPORT FOR DENT OF KOWA EMORI HP01D2000 CARTON BOX

DIRECT CAUSE PROCESS/MATERIAL W1- Dent is due to the stripping blade.

W2- Because the edge of stripping blade is pointed and blade is little bit in upward position, when the Printed Board is pulled by gripper it caused dent to the item.





INDIRECT
CAUSE
(OUTFLOW)

W1- Operator did not noticed immediately the dent since they only conduct sampling checking and when they saw the dent they immediately stop the process, pushed the Stripping Blade downward and put adhesive and paper tape.

PROCESS/MATERIAL W2- Operator removed some of worst dent and included for them is accepted.

PRODUCTION CORRECTIVE ACTION

Removed the pointed part of Stripping Blade and make it round curved using Grinder Machine.



PIC:

PRODUCTION

TARGET DATE:

211016

PREPARED BY:

GERALD DE GUZMAN PROD ASST. SUPERVISOR APPROVED BY:

WEENA A APALLA SR. SUPERVISOR

UPDATES:

STRIPPER BLADE ROUNDED CORNERS:



