

## INVESTIGATION REPORT FOR PEEL-OFF OF 516297700 LOUVRE 2 MDX ASIA

### DIRECT CAUSE METHOD (PROCESS)

W1: During running the glue viscosity was changing (low viscosity)

W2: It is possible to have changes in glue viscosity.

W: When glue viscosity is low, there is an impact to encountered splashing.

## PRODUCTION ACTION PLAN

- > Check viscosity if there is a top-up.
- > Putting splashing cover in the bottom area.

Prepared by:

PRODUCTION IE

Reviewed by:

Noemi Cepeda  
PRODUCTION SUPERVISOR