INVESTIGATION REPORT FOR INVERTED CUT OF 514471900 CARTON BOX	
DIRECT CAUSE	W1: During process there is a possibility to have wrong orientaion of panels.
METHOD (PROCESS)	W2: Feeder operators did not do checking of panels that may occur inverted cut.(Human Error)

PRODUCTION ACTION PLAN

Immediate Action:

> Reorientation to Diecut operators regarding to inverted cut encountered



Prepared by:

Reviewed by:

PRODUCTION IE

Noemi Cepeda
PRODUCTION SUPERVISOR