

INVESTIGATION REPORT FOR MISALIGNED CUT OF 516512900 LIGHT MB US


DIRECT CAUSE METHOD (PROCESS)

- W1: Misaligned cut occurred due to excess PS and SF.
- W2: Encountered problem in setting-up of side guide on diecut machine.
- W3: The problem were connected in Lamination alignment.



PRODUCTION ACTION PLAN

- > To put remarks on JO if left or right alignment
- > Lamination and diecut operators will followed right alignment
- > Meeting with Lamination and Diecut operators
- > Endorsement for night shift.



Prepared by:

PRODUCTION IE

Reviewed by:

Noemi Cepeda
PRODUCTION SUPERVISOR