
INVESTIGATION REPORT FOR PEEL OFF AT 516412001 CARTON BOX	
(DETACHING)	
DIRECT CAUSE	W1: During process, operator do bundling on detaching. It is posible that peel off occur when facing of item are inverted (smooth surface face down) while detaching. W2: Wrong Method on handling or detaching of item. (smooth surface face upward-detached downward while rough surface face upward-detached upward.)
	W1: During Process of detaching it is posible to have peel off when the die cutted items are uncut. W2: It is posible that the blade used for die-cut is worn out.



PRODUCTION ACTION PLAN

> Orientation for peel off due to detaching.