


INVESTIGATION REPORT FOR SCRATCH OF RX1-4516-000 Z10 CARTON - CANON

DIRECT CAUSE	W1: The scratches occur when the item passing through conveyor for applying hotmelt glue. Folder
METHOD (PROCESS)	operator detect the scratches.



JO #: JO-09072
 Input Qty.: 404
 Reject Qty.: 90 pcs.
 Rejection Rate: 22.27%

PRODUCTION ACTION PLAN

- > Segregation of detected defect and inform inline QA
- > call the attention of PIC/Leader for any abnormality encountered.
- > Inform engineering personel for the repair of the said rough surface at machine

KANEPACKAGE PHILIPPINE, INC.

ATTENDANCE SHEET


Submitted by: Date:

ACTIVITY:

Attendees			
NO.	FIRST NAME	LAST NAME	SIGNATURE
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			



Rough surface



Flatten rough surface