## **INVESTIGATION REPORT FOR UNCUT RX1-4516 CARTON BOX**

## DIRECK CAUSE:

W1: UNCUT ON ITEM AT ETTERNA DIE CUT.



W2: UNCUT ITEM DETECTED AT DIE CUT PROCESS DURING RUNNING. THEY SEGREGATE IT ON A CASTER WITH HOLD TAG ON THE TOP OF THE ITEM. IT IS POSIBLE THAT DURING RUNNING AT GLUING PROCESS, OPERATOR LOOK FOR THE PARTNER OF PANEL A AND THEY DID NOT NOTICE/CHECK THE TAG ON THE TOP OF THE ITEM.



W3: NO PROPER ENDORSEMENT ON THE HOLD ITEM.

## DIRECK CAUSE:





W2: WRONG PATERN SHEETT CAUSE BY WRONG PICKING.



W3: HUMAN ERROR

## **PRODUCTION ACTION PLAN**

> ORIENT THE OPERATOR REGARDING TO THE ISSUE OF UNCUT AND CHECKING OF LABEL/TAG



> ACTION TAKEN: CHANGE THE PATTTERN SHEETT IMMEDIATELY.

> PUT HOLD TAG ON THE TOP OF THE ITEM FOR IDENTIFICATION OF ITEM. >SUB LEADER VERIFYYY THE SHEET TO BE USED.



