

# **INVESTIGATION REPORT**

Prepared By:	Check By:	Approved By:	
·		_	
C. Arevalo/ M. Vito	G. Magsino	R. Miranda	
OA-IE/ Production IE	OA Supervisor	KPLIMA Gen. Operation Mgr.	

## ROBLEM DESCRIPTION 1.1. ISSUE:

DATE:

1.2. ITEM DESCRIPTION:

PART CODE:

515715400 LIONEL FPY ICB FOR AMERICA PART NAME:

### 1.3. BACKGROUND:



20-Oct-22

- >Date Encountered: 221019
- >Lot qty.: 180ea
- >Reject qty.: 31ea >Reject percentage: 17.22% >Machine#: Gluing machine 4

Remarks:

Scratches occured at upper flap class B (Blue Background) at panel B portion.

11. 1	II. IMMEDIATE ACTION					
	ACTION ITEMS	Target Date:	Person In-charge			

### III. WHY WHY ANLYSIS DETAILS:

- **DIRECT CAUSE:**WHY 1: Scratches at semi-auto gluing process.
- WHY 2: During running, the item hang at the feeder area that can cause scratches on the upper flap.
- WHY 3: Operator did not notice the loose guide at the feder area.
  WHY 4: The guide loose cause of the vibration of the machine and posible that the spacer is not in good condition and need to replace.





**Spacer** 

### IV. CORRECTIVE ACTION:

## DIRECT CAUSE:

1. Orient the operator regarding to the issue of scratches for awareness.



2. Putting of Cable tie on the Guide for temporary usage.



3. Request for the replacement of spacer to Engineering. Target date: 2nd week of November.