

03-Nov-22

INVESTIGATION REPORT

Prepared By:		Check By: Approved By:			
ı					
ı					
	C. Arevalo/ G. Sayas	G. Magsino	R. Miranda		
ı	QA-IE/ Production IE	QA Supervisor	KPLIMA Gen. Operation Mgr.		

I. PROBLEM DESCRIPTION

DATE:

ADDLEM DESCRIPTION				
1.1. ISSUE:				
WRONG FLUTE COMBINATION				
1.2. ITEM DESCRIPTION:				
PAD BLOCKS				
1.3. BACKGROUND:				

INHOUSE DETECTION: WRONG FLUTE COMBINATION LOT SIZE: 260 PCS REJECT QUANTITY: 156 REJECTION RATE: 60% REMARKS: Wrong flute combination occurred on pad blocks with combination of: Top-4CF; Bottom-4BF and Top-3CF and

II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge

III. WHY WHY ANLYSIS DETAILS:

DIRECT CAUSE:

WHY 1: Wrong flute combination occurred on pad blocks with combination of: Top-4CF; Bottom-4BF and Top-3CF and Bottom 4BF+1CF WHY 2: There's a possibility that the operator miscount the sheets while feeding.





IV. CORRECTIVE ACTION:

- > Re orient the operator regarding the issue. > Additional checkboint of the catcher.