

11-Nov-22

# **INVESTIGATION REPORT**

Prepared By:	Check By:	Approved By:	
C. Arevalo/ G. Sayas	G. Magsino	R. Miranda	
QA-IE/ Production IE	QA Supervisor	KPLIMA Gen. Operation Mgr.	

#### I. PROBLEM DESCRIPTION

DATE:

Fax No. (049) 545-6302

1.1. ISSUE:

| GLUE STAIN |
1.2. ITEM DESCRIPTION:
| PART CODE: | 516182300 |
| PART NAME: | LINUS FAL ASIA |

1.3. BACKGROUND:



INHOUSE DETECTION: Glue Stain LOT SIZE: 300 PCS REJECT QUANTITY: 140 REJECTION RATE: 46.67% JO: 25010 REMARKS: Glue Stain occured on the bottom flap and on the back surface of the panel.

### II. IMMEDIATE ACTION

I AL II LEPANTE NOTAVIT				
ACTION ITEMS	Target Date:	Person In-charge		

### III. WHY WHY ANLYSIS DETAILS:

#### **DIRECT CAUSE:**

WHY 1: Glue Stain occured on the bottom flap and on the back surface of the panel.

WHY 2: There's a possibility that the plate is accumulated with glue

WHY 3: The operator failed to notice if the glue plate is still in good condition





## IV. CORRECTIVE ACTION:

- > Orient the operators regarding the issue.
- > Setting a standard of weekly checking and cleaning of glue plate.

