KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69					INVESTIGATION REPORT FORM (IRF)					
					Inhouse Detection Customer Claim					
		No. (049) 545-6302		- Leader	ol No.: 622	511	Date Iss		09 12	
Custon	ner		. KOWA EMORI	Attent	en començations de			ald De Guzr		
Item Co	ode		HP01D2000-3	Depar				RODUCTIC		
Item De	escription		OUTER BOX	Date of Detection 22 09 10						
Job Or	der Number		JO22-M-01859-5	Section	n Detected		QA	-SCREENI	NG	
		ILLUSTRATION C	DF THE PROBLEM		Major			Minor		
ESI SI CEPINE	Literatura	T		L	ot Quantity (pcs.)	Re	eject Quantity (pcs	s.)	Reject Percentage	
			3	N 1 1 1 1 1 1	9,000	2004-1916 1951	86		0.96%	
Murata Products				Natur	e of Defect:					
				MISALIGN GLUE						
				Requirement:						
				Must not exceed or far from the creasing line.						
				Actua						
				some exceeded the creasing line while the others are far and misalign from the creasing line.						
	NO. OF OC	CCURRENCE	DISPOSITION		AREA OF OC	CURREN	CE / ORIGIN		CONTENT	
	First		Hold		Slotter		Gluing		Material	
	Recurrence		Special Acceptance		EQOS		Vertical		Dimension	
	No.:		For Rework		Diecut		Others:	1112	Appearance	
	Date:		Reject / Disposal		Detaching				Process / Method	
	Issu	ued by	Checked by		Approved	d by			eived by iving Section)	
								41	4 _	
	Rochelle	Evangelista	Roderick Ramos		Rexel Alm	nario 📈		Gerald I	De Guzman	
	QA-1	E Staff	QA Sr. Supervisor	NAME AND ADDRESS OF THE PARTY.	QA Asst. Ma	anager		Head/	Supervisor	
			I. INVESTIGATI	ON / A	NALYSIS					
	DIRECT CAU	JSE: (Analyze the reas	on of occurrence, why it happened?)		INDIRECT CAU	SE: (Analy:	ze the reason of c	ccurrence,	why it leaked?)	
D)	Why 1:			Why 1:						
rainin	Why 2:		.\/	Why 2:			.1/			
System / Training	Why 3:	N/A					NA			
Syste	Why 4:									
	Why 5:	hy 5:								
S	Why 1:	1:								
Design / Toolings	Why 2:	P/A					11975			
Jn / Te	Why 3:	* / A					NA			
Desig	Why 4:	E								
	Why 5:	hy 5:								
a	Why 1:			Why 1:						
/lateri	Why 2:	010 0	~ / :	Why 2:			EE ATTA	\$		
Process / Material	Why 3:	PLS. 7	E ATTAGLED	Why 3:	III	PLS. S	EE ATTA	CrteD		
Proce	Why 4:			Why 4:						
_	M/by 5			MAN F						

P

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

Fax No. (049) 5	45-6302							
FINAL CON								
C	OCCURRENCE ROOTCAU	SE			OUTFLOW ROOTCAUSE			
TO CRETSI	ALIGN THE GL		000	- RA	NOOMLY OCCUPENCE.			
IMMEDIATE ACTION: (A	ction to be done to contain/ tempo	orary correct the pro	oblem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)				
A. Sorting Result					Actions to be done to eliminate recurrence	Who / When		
Loca	ation Total Stock	NG	Total Good					
RM				System	2/4			
WIP				System				
FG					ers graf cap (la opa, e mable to se	Etan ber		
B. Orientation								
Date	Time				P/A			
Title				Tools				
Attendees								
C. Reworking					this large is a second or see a second	-12-1		
Rework Quantity	(1)			Process	PLS. SEE ATTACKE	D I		
Total Good								
Rework Percentage (Good)								
II. QA ROOTCAUSE V	ERIFICATION (To be filled	out by QA In-	charge)	Date Conduct				
	Identified Rootcause			Recommendation				
WHEN THE CHARSING FUR HTT THE GRAIN SIREONON THERE IS A TENDESCY THAT THE IT WILL WIS AVION.				NA				
	III. CORF	RECTIVE ACTIO	N VERIFICATION	ON (To be fille	ed out by QA In-charge)			
	Checked by	Date	Implem	ented?	Remarks			
1st Verification of Action	R. EVANUEUS TA	220913	Yes	[] No				
2nd Verification of Action			[]Yes	[] No				
3rd Verification of Action			[]Yes	[]No				
Effectiveness of Action			[] Yes	[] No				
Note: If no same defects / pa deliveries or 3rd verification	roblems occurs for 5 consec of action still not yet implen	cutive deliveries nented, Investiga	I , corrective action ation Report sha	on is considere	ed effective / closed. If the same problem occurs wi I to the affected department to provide new improve	thin 5 consecutive ement action.		
			IV. CLO	SURE				
BILLUS: QUALITY AS	SURANCE DEPAR	TMENT	Approv	ed by:	Process Owner Acknowledgment:	(Receiving Section)		
Clased				Ano-	:			
Str Open		DASUR	pervisor	QA Asst.	Manager Line Leader D	epartment Head		
Re Issue IRE DAYE AND				Date: 22 [20]		оранитени педи		
SIGNATURE 2	क्षेत्रक उन ॥११	9		-V -				

INVESTIGATION REPORT FOR EMORI HP01D2000-3 MISALIGNED GLUE


	W1	There is instances that the creasing got misalign once the creasing rule hit the grain direction line of the board which is hard portion.
DIRECT CAUSE PROCESS/MATERIAL	W2	This instances may caused difficulty to align the glue tab and need pre folding or "hilot".
	W3	Since operator got difficulty to align the glue tab its unavoidable to encounter random of misalign gluing.

INDIRECT CAUSE (OUTFLOW) PROCESS/MATERIAL	AA T	Since the occurrence is random and this item was 2-line running in SD-1800 there is outflow happened.	
---	------	---	--

PRODUCTION CORRECTIVE ACTION

I) ORIENT AND ALERT THE OPERATOR PEGARDING THIS ISSUE.

2) Put nick mark in the Glue Tab for additional gluing alignment reference to operator.



PIC: Production TARGET DATE: Discuss in 4pm meeting

PREPARED BY:

GERALD DE GUZMAN
PROD ASST. SUPERVISOR

APPROVED BY:

WEENA V. APALLA
ASST. MANAGER

220913