	- 1			1			× ,	
	No. 5 Ring Roa	d LISP II, Brgy. L (049) 545-7166 t	SE PHILIPPINE INC. a Mesa, Calamba City, Laguna o 69	Inhous	e Detection		omer Claim	
				Control No.:	592	Date Issued:		
Custom	tomer CANON			Attention To		Gerald I	De Guzman	
Item Co	m Code RX1-5756-000			Department Production			duction	
Item De	scription		Z10 CARTON BOX	Date of Detection 22 07 07			07 07	
Job Ord	ler Number	JO-F-	22 - 224 - 11	Section Detected PRD-MANUAL GLUING			UAL GLUING	
	ILLU	JSTRATION O	F THE PROBLEM	Major		Mino	or •	
				Lot Quan		Reject Quantity (pcs.)	Reject Percentage 8.90%	
			Product Nun	Nature of Defe	ect:			
						PEEL OFF		
	In			Requirement:				
				Maximum of 20mm diameter for peel off				
				Actual:				
				exceeded the maximum requirement for peel off				
	NO. OF OCCURRE	NCE	DISPOSITION	ARI	EA OF OCCU	RRENCE / ORIGIN	CONTENT	
	First		Hold	Slotter		Gluing	Material	
	Recurrence		Special Acceptance	EQOS		Vertical	Dimension	
	No.:		For Rework	Diecut		Others:	Appearance	
	Date:		Reject / Disposal	Detac			Process / Method	
	Issued by		Checked by		Approved by		Received by	
	issued by		110				(Receiving Section)	
	QX -		May 220711.				Ast	
	Rochelle Evangel	ista	Roderick Ramos		Rexel Almaria		Gelald De Guzman Head/ Supervisor	
	QA-IE Staff		QA Sr. Supervisor		A Asst. Mana	ger /	nead/ Supervisor	
				TION / ANALYSI		(0. 1. 1)	www.s. why it looks d2)	
	DIRECT CAUSE: (Ar	alyze the reaso	on of occurrence, why it happened?)	STATE OF THE STATE	ECT CAUSE:	(Analyze the reason of occu	irrence, why it leaked?)	
Б	Why 1:			Why 1:				
System / Training	Why 2:			Why 2:		9 /		
T/ma	Why 3:			Why 3:		D/A		
Syste	Why 4:			Why 4:				
	Why 5:			Why 5:				
	Why 1: Why 2: Why 3:			Why 1:				
Design / Toolings				Why 2:		41/		
J/To				Why 3:		N/A		
esign	Why 4: Why 5:		Why 4:					
			Why 5:					
	Why 1:			Why 1:				
erial	Why 2:			Why 2:			•	
Why 2: Why 3: Why 4:			Why 3:	PLS.	SEE ATTACH	E)		
cess		,	5	Why 4:				
Pro	Why 4:			Why 5:				

KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

			FINAL CON	CLUSION	20	
0	CCURRENCE ROOTCAUSE		OUTFLOW ROOTCAUSE			
- DULL	WITTING 8	HADE	- RECURRING OCCUPATION			
IMMEDIATE ACTION: (A	ction to be done to contain/ tempora	ry correct the prob	lem found)	CORRECT	IVE ACTION: (Actions to be done to ensure that the problem will not h	appen again) 🔹
A. Sorting Result					Actions to be done to eliminate recurrence	Who / When
Loca	ation Total Stock	NG Total Good				
RM A	1. N.	N/	W /	System P/A		
WIP	A A	A	A			
FG	/	1	/			
B. Orientation						
Date 7/14	7/14/20 Time .		Design / Tools	r/4		
Title tooling	tooling ustradion accomment regarding blade replace				, ;	
Attendees how	ing wandon					
C. Reworking						
Rework Quantity N 6				Process	PLS. SEE ATTACHED	
Total Good	A	·				
Rework Percentage (Good)						
II. QA ROOTCAUSE V	/ERIFICATION (To be filled	out by QA In-c	harge)	Date Conduct	ed: 7/11/22 PIC: QA 15	
	Identified Rootcause				Recommendation	
PM	cutting blade				M	
	III. CORRE	ECTIVE ACTIO	N VERIFICAT	ION (To be fille	ed out by QA In-charge)	
	Checked by	Date	Implen	nented?	Remarks	
1st Verification of Action	aa w	7/H/22	[]Yes	[/No	no remirde signage in Die unt	5700

	Checked by	Date	Implem	ented?	Remarks
1st Verification of Action	aa ie	7/H/22	[]Yes	[/No	no reminde signage in Die unt St700
2nd Verification of Action	0A (<	7/19/22	[/Yes	[] No	REMINDER IN S1700 attoured Pased
3rd Verification of Action		- 1:-	[]Yes	[] No	ACTO
Effectiveness of Action			[]Yes	[] No	


Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE								
QUALITY ASSURPANCE UPPART	Approved by:	Process Owner Acknowledgment: (Receiving Section)						
Clased Still Open Re-Issue IRF	QA Supervisor QA Asst. Manager Date: 22/20	Line Leader Department Head Date: Date:						


INVESTIGATION REPORT FOR CBMP RX1-5756-000 Z10 CARTON PEEL OFF

DIRECT CAUSE	W1	Due to the hardness of materials the cutting blade in Slot portion get dull.
PROCESS/MATERIAL	W2	Dull cutting blade result to Uncut then result to Peel Off the items since the item underwent auto stripping process in Diecut S1700.

INDIRECT	W1	When operator notice the Peel Off they immediately attached backing tape on the affected area.				
CAUSE		Peel off recurring in different location of slot and since occurrence is randomly there is out flow happened.				
(OUTFLOW) PROCESS/MATERIAL	14/2					



PEEL OFF RECURRING IN DIFFERENT LOCATION



DIE-BLADE ALREADY HAVE STEEL BACKING TAPE ATTACHED WITH A SETUP PRESSURE OF 95 AND TOTAL OF 33,096 SHOTS

PRODUCTION CORRECTIVE ACTION

- 1. Assessment of tooling custodian is blade replacement since all the slot have steel backing tape due to dull cutting blade.
- 2. Put Reminder signage in Diecut S1700 to be alert for the items underwent auto stripping since it was prone to Peel Off, specially CBMP items with hard materials and wave cutting blade. (7/19) 20 は) DONE

PIC: PRODUCTION TARGET DATE: 220714

PREPARED BY:

SERALD DE GUZMAN
PROD ASST. SUPERVISOR

APPROVED BY:

WEENA V APALLA
ASST. MANAGER