

17-Nov-22

## **INVESTIGATION REPORT**

Prepared By:	Check By:	Approved By:
K.DIAZ		
OA-IE/ Prodn IE	OA/ Prodn SV	KPLIMA Operations Gen. Mngr.

5M REVIEW		DOCUMENT REVIEW					
MAN		Affected Document:	Date Reviewed:	Disposition:		PIC:	Target Date:
MACHINE		Procedure Manual		☐ With Revision	☐ No Revision		
MATERIAL		Work Instruction		☐ With Revision	□ No Revision		
METHOD		Process Flow		☐ With Revision	☐ No Revision		
ENVIRONMENT		Forms		☐ With Revision	☐ No Revision		

# I. PROBLEM DESCRIPTION 1.1. ISSUE:

BURSTING

1.2. ITEM DESCRIPTION:
PART CODE:
PART NAME:
1.3. BACKGROUND:

516297800 LOUVRE 2 MDX ASIA

DATE:



#### DETAILS:

>Inhouse Detection : Bursting

>Lot size: 1800pcs > Reject Qty: 312pcs >Rejection Rate: 17.33%

>JO#: 25706

Remarks: Bursting occurred on the creasing

#### II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge

#### III. WHY WHY ANLYSIS DETAILS:

### DIRECT CAUSE:

WHY 1: Bursting occurred on the creasing part of the item.
WHY 2: The nickmark on the blade was little and the scrap might loose .
WHY 3: There was a scrap left on the plate while running the item.





## IV. ACTION PLAN:

- > Adding a nickmark in the cutting area from 1mm to 1.5mm by tooling.
   > The tooling custodian already PR new blade (Nov 25, 2022)





### INDIRECT CAUSE: