

12-Oct-22

INVESTIGATION REPORT

Prepared By:		Check By:	Approved By:		
	C. Arevalo/ G. Sayas	G. Magsino	R. Miranda		
	OA-IE/ Production IE	QA Supervisor	KPLIMA Gen. Operation Mgr.		

I. PROBLEM DESCRIPTION

DATE:

ROBLET DESCRIPTION					
1.1. ISSUE:					
	PEEL OFF				
1.2. ITEM DESCRIPTION:					
PART CODE:	516228600				
PART NAME:	LOUVRE 2 MCX ETD				
1.3. BACKGROUND:					

N/A

II. IMMEDIATE ACTION

I IMPLEDIATE ACTION					
	ACTION ITEMS	Target Date:	Person In-charge		

III. WHY WHY ANLYSIS DETAILS:

DIRECT CAUSE:

- WHY 1: Peel off occurred on the item.
- WHY 2: a. The cell belt they were using is sharp since it is new.
- b. The old cell belt is smooth so delay feeding of boards occur.
 WHY 3: a. The operator didn't notify the peel off during running.



CELL BELT

IV. CORRECTIVE ACTION:

- > Putting paper tape on the cell belt to avoid the occurrence of peel off on the items specially when the belt is new.
- > Orient the operator regarding the issue of peel off due to changes of new cell belt at the feeder area.



