

12-Oct-22

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:		
C. Arevalo/ G. Sayas	G. Magsino	R. Miranda		
OA-IF/ Production IF	OA Supervisor	KPLIMA Gen. Operation Mgr.		

I. PROBLEM DESCRIPTION

DATE:

1.1. ISSUE:				
	PEEL OFF			
1.2. ITEM DESCRIPTION:				
PART CODE:	516512900			
PART NAME:	LIGHT2 MB ICB FOR AMERICA			
1.3 BACKCDOLIND:				

N/A

II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge

III. WHY WHY ANLYSIS DETAILS:

DIRECT CAUSE:

- WHY 1: Peel off occurred on the item class A printer image due to splashing.

- WHY 2: a. The provided splashing cover for Light items is just a paper.

 b. There's a posibility that the splashing cover filled its capacity.

 WHY 3: a. During running, even if the glue is in its standard viscosity, there is still a chance that splashing will occur.

 WHY 4: a. The operator failed to check the splashing cover that might be the reason why some glue dripped with other items.



SPLASHING COVER

INDIRECT CAUSE:

WHY 1: There is no fabricated splashing cover for Light items.

IV. CORRECTIVE ACTION:

- > Orient the operators to check. clean and change the splashing cover every 500 sets. > Work request for fabricated splashing cover for light items. (Target date: Octob (Target date: October 22, 2022) (With work request to engineering)

All single face for light items (No fabricated splashing cover) Louvre 2, Lime FB, Lime MB (With fabricated splashing cover)



