


# INVESTIGATION REPORT FOR DELAMINATION OF PAD BLOCKS

DIRECT CAUSE METHOD (PROCESS)	W1: Vertical operator encounter delamination of Pad blocks during cutting. W2: At lamination process, the glued item must be placing on provided jig one by one (5 for B-flute & 3 for C-flute) W3: The occurrence of having delamination of pad blocks when the item having insufficient application of glue that can cause of detach/delam. W4: It is possible that the the setting of glue application and the speed was change.
----------------------------------	--



## PRODUCTION ACTION PLAN

- > Rework the item.
- > re-orient operator regarding issue Delamination at pad blocks due to weak glue

**KANEPACKAGE PHILIPPINE, INC.**

**ATTENDANCE SHEET**

Submitted by: Yan, Sheng Date: 10/10/2023

ACTIVITY: REWORKING, LAMINATING, AND FINISHING (PAD BLOCKS)

Attendees			
NO.	FIRST NAME	LAST NAME	SIGNATURE
1	Yan	Kellogg	
2	Reynald	Reynald	
3	Kelley	Reynald	
4	Yan	Reynald	
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			

GA-005-F13 Rev. 00 Page 1 of 1