KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

230502

INVESTIGATION REPORT

| Prepared By: | Check By: | Approved By: | |
|-----------------|--------------|------------------------------|--|
| MHVITO | N. CEPEDA | R. MIRANDA | |
| OA-IE/ Prodn IE | QA/ Prodn SV | KPLIMA Operations Gen. Mngr. | |

| 5M | REVIEW | DOCUMENT REVIEW | | | | |
|-------------|----------------------|--------------------|----------------|-------------------------------|---------|--------------|
| MAN | No Changes | Affected Document: | Date Reviewed: | Disposition: | PIC: | Target Date: |
| MACHINE | No Changes | Procedure Manual | | ☐ With Revision ☐ No Revision | MH.VITO | N/A |
| MATERIAL | SCRATCHES AT PANEL A | Work Instruction | 230307 | ☐ With Revision ☐ No Revision | MH.VITO | N/A |
| METHOD | No Changes | Process Flow | 230307 | ☐ With Revision ☐ No Revision | MH.VITO | N/A |
| ENVIRONMENT | No Changes | Forms | | ☐ With Revision ☐ No Revision | MH.VITO | N/A |

I. PROBLEM DESCRIPTION

| 1.1. ISSUE: | | | |
|------------------------|--------------|--|--|
| | SCRATCHES | | |
| 1.2. ITEM DESCRIPTION: | | | |
| PART CODE: | 516297700 | | |
| PART NAME: | LOUVRE 2 MDX | | |
| 1.2 PACKCROUND: | | | |

1.3. BACKGROUND:

PICTURE

DATE:





DETAILS:

> SCRATCHES AT PANEL A LOUVRE

2MDX 516297700

-SCRATCHES AT UPPER FLAP CLASS B

-LOT QTY: 689 EA -REJECT QTY: 69 EA

-REJECT PERCENTAGE: 10.01%

II. IMMEDIATE ACTION

| ACTION ITEMS | Target Date: | Person In-charge |
|---|--------------|--------------------|
| GLUING OPERATOR REPORT THE ABNORMALITY ENCOUNTER AT GLUING MACHINE 4 FOR THE ISSUE OF SCRATCHES AT PANEL A AND CONDUCT RETRIAL. | 230325 | Gluing Operator/QA |
| SEGREGATION OF REJECT ITEM(SCRATCHES) AND CHANGE PLAN | 230325 | Gluing Operator/QA |

III. CAUSE ANALYSIS:

| WHY 1: | SCRATCHES OCCURRED ON ITEM 516297700 LOUVRE 2 MDX PANEL (A) AT UPPER FLAP CLASS B. | |
|--------|---|--|
| WHY 2: | SCRATCHES WAS OBSERVED DURING MASS PRODUCTION AND THE OPERATOR IN-CHARGE IMMEDIATELY STOP RUNNING AND CONDUCT RETRIAL. NOTE: TO CHECK IF THERE IS A PROBLEM WITH THE SET-UP, THEY CHANGE THE LOCATION OF PANEL A AND B, BUT STILL PANEL A HAS SCRATCHES. | |
| WHY 3: | UPON SETTING OF THE ITEM AGAIN TO ITS STANDARD SET-UP, GOOD OUTPUT WAS ACHIEVED. | |

IV. ACTION PLAN:

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

230502

DATE:

INVESTIGATION REPORT

| Prepared By: | Check By: | Approved By: | |
|-----------------|--------------|------------------------------|--|
| MHVITO | N. CEPEDA | R. MIRANDA | |
| QA-IE/ Prodn IE | QA/ Prodn SV | KPLIMA Operations Gen. Mngr. | |

| 1 | DO MANUAL GLUING TO THE ITEM FOR THE REAMAING PANELS | 230325 |
|---|---|--------|
| 2 | REMIND THE OPERATOR TO THE ABNORMALITY ENCOUNTER TO THE PROCES REGARDING TO THE ISSUE OF SCRATCHES. | 230325 |
| 3 | HOLD THE ITEM AND CHANGE THE PLAN WHILE WAITING FOR APROVAL | 230325 |