KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

230405

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:	
MHVITO	N. CEPEDA	R. MIRANDA	
QA-IE/ Prodn IE	QA/ Prodn SV	KPLIMA Operations Gen. Mngr.	

5M REVIEW		DOCUMENT REVIEW				
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual	230405	☐ With Revision ☐ No Revision	MH.VITO	N/A
MATERIAL	No Changes	Work Instruction		☐ With Revision ☐ No Revision	MH.VITO	N/A
METHOD	WRONG SET-UP	Process Flow		☐ With Revision ☐ No Revision	MH.VITO	N/A
ENVIRONMENT	No Changes	Forms		☐ With Revision ☐ No Revision	MH.VITO	N/A

I. PROBLEM DESCRIPTION

1.1. ISSUE: **SCRATCHES** 1.2. ITEM DESCRIPTION: PART CODE: 516041100 **PART NAME:** LIONEL F ASIA

1.3. BACKGROUND:

PICTURE

DATE:



Scratches

DETAILS:

- > SCRATCHES AT GLUING MACHINE 4 LIONEL ASIA
- -SCRATCHES AT UPPER FLAP CLASS B
- -LOT QTY: 879 EA -REJECT QTY: 21 EA
- -REJECT PERCENTAGE: 2.39%

II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
Re-setting of feeder roller AND TRIAL	230502	OPERATOR

III. CAUSE ANALYSIS:

WHY 1:	SCRATCHES OCCUR AT UPPER FLAP CLASS B OF LIONEL USING GLUING M,ACHINE 4
WHY 2:	UPON CHECKING OF THE SCRATCHES PROBLEM, FEEDER ROLLER IS NOT GOOD IN SET-UP (LOWER SET-UP FEEDER GUIDE)
WHY 3 OPERATOR FAILED TO MEET THE REQUIRED HEIGHT OR ADJESTMENT OF THE BOARD AT FEEDER AREA (ADJUSTMENT THE THICKNESS OF THE BOARDS).	

IV. ACTION PLAN: V. EVIDENCES:

1	REMIND THE OPERATOR REGARDING SCRATCHES DUE TO WRONG SET-UP OR ADJUSTMENT OF STOPPER GUIDE (FEEDER GUIDE) AT FEEDER AREA.	230505	
2	POST AN EYE MARK (OPL) AT FEEDER AREA	230507	



230405

DATE:

INVESTIGATION REPORT

Prepared By:	Check By: Approved By:		
MHVITO	N. CEPEDA	R. MIRANDA	
QA-IE/ Prodn IE	QA/ Prodn SV	KPLIMA Operations Gen. Mngr.	