KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

230509

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:	
K.N. ACUIN	N. CEPEDA	R. MIRANDA	
OA-IF/ Prodn IF	OA/ Prodn SV	KPLIMA Operations Gen. Mngr	

5M REVIEW		DOCUMENT REVIEW				
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		☐ With Revision ☑ No Revision	KN ACUIN	N/A
MATERIAL	No Changes	Work Instruction	230509	☐ With Revision ☑ No Revision	KN ACUIN	N/A
METHOD	no proper checking of sheets	Process Flow	230309	☐ With Revision ☑ No Revision	KN ACUIN	N/A
ENVIRONMENT	No Changes	Forms		☐ With Revision ☐ No Revision	KN ACUIN	N/A

I. PROBLEM DESCRIPTION

1.1. ISSUE:		
	PEEL OFF DUE TO EXCESS GLUE IN 1ST GLUING	
1.2. ITEM DESCRIPTION:		
PART CODE:	5159121-00	
PART NAME:	LOUVRE 2 MJX ICB FOR AMERICA	

1.3. BACKGROUND:

DATE:

PICTURE

90. **O** | *

DETAILS:

> EXCESS GLUE DETECTED IN 1ST GLUING > AT MACHINE GLUING 4 >LOT QTY 598 EA >REJECT QTY: 21 EA MAJOR REJECT /DETECTED BY QA

II. IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
ADJUST (THINNED) THE APPLICATION OF GLUE IN 1ST GLUING	230508	OPERATOR
SORT THE ITEMS	230508	OPERATOR AND QA

III. CAUSE ANALYSIS:

WHY 1:	EXCESS GLUE THAT RESULT TO PEEL OFF OF THE ITEM IN GLUING MACHINE 4	
WHY 2:	THE OPERATOR (CATCHER) PUT TOO MUCH APPLICATION OF WHITE GLUE IN THE 1ST GLUING DURING MASS PRODUCTION	
WHY 3:	THE OPERATOR (CATCHER) DIDN'T NOTICED THE EXCESS GLUE IN THE GLUE TAB	
WHY 4:	THE OPERATOR INCHARGE WAS STILL UNDER TRAINING & NO PROPER ORIENTATION	

IV. ACTION PLAN: V. EVIDENCES:

1	RE EDUCATE THE OPERATOR ABOUT THE WORK I	230515