# KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

MAY 18, 2023

Fax No. (049) 545-6302

**INVESTIGATION REPORT** 

Prepared By:	Check By:	Approved By:
K.DIAZ	N. CEPEDA	R. MIRANDA
OA-IF/ Prodn IF	OA/ Prodn SV	KPLIMA Operations Gen. Mngr

5M REVIEW			DOCUMENT REVIEW			
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		☐ With Revision ☐ No Revision	K. DIAZ	N/A
MATERIAL	No Changes	Work Instruction		☐ With Revision ☐ No Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow		☐ With Revision ☐ No Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		☐ With Revision ☐ No Revision	K. DIAZ	N/A

### I. PROBLEM DESCRIPTION

1.1. ISSUE:		
	Damage	
1.2. ITEM DESCRIPTION:		
PART CODE:	516512700/51651300	
PART NAME: LIGHT 2 FA America/Light 2 MB America		
1.3. BACKGROUND:		

**DATE:** 

# PICTURE



# DETAILS:

>Inhouse Detection :DAMAGE

>Lot size: 2072 > Reject Qty: 48pcs >Rejection Rate: 2.32%

### **II. IMMEDIATE ACTION**

ACTION ITEMS	Target Date:	Person In-charge
Line Leader Immidiately inform Diecut Sub-Leader and operator for Misalign cut.	May 19, 2023	Sub-leader and Die cut operator

## **III. CAUSE ANALYSIS:**

	WHY 1: Damage occured during manual detaching process. Note: In 2 J.O found 48 pcs reject out of 2072 pcs	
WHY 2: Due to uncut ,The damage appears on the sedge of the item.  Note: The operator did not follow the standard scrap removal count on the manual detaching item.		
WHY 3	Due to not having the standard amount of pulling power, it shocks and interacts with each item that result damage.	

#### **IV. ACTION PLAN: V. EVIDENCES:**

1	Follow the standard number of of item in removing scrap PIC: Operator Target Date: May 19, 2023	
2	Reorient about telling the operator the proper detach of items and proper placing of detach item in the wip area.  PIC: Production IE  Target Date: May 19, 2023	*Please see attached on next sheet*