### KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

# **INVESTIGATION REPORT**

Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302		Prepared By:	Check By:	Approved By:
DATE:	JULY 27 2023	K.DIAZ OA-IE/ Prodn IE	N. CEPEDA QA/ Prodn SV	R. MIRANDA KPLIMA Operations Gen. Mngr.
				KPEIMA Operations Gen. Milgr.

5M REVIEW		DOCUMENT REVIEW				
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		<ul> <li>With Revision</li> <li>With Revision</li> </ul>	K. DIAZ	N/A
MATERIAL	No Changes	Work Instruction		With Revision With Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow		With Revision With Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		With Revision V No Revision	K. DIAZ	N/A

#### I. PROBLEM DESCRIPTION

1.1. ISSUE:			
	Damage		
1.2. ITEM DESCRIPTION:			
PART CODE:	516513000 / 515913300		
PART NAME:	LIGHT 2 MB AMERICA / LOUVRE 2 MJX		
1.3. BACKGROUND:			
PICTURE	ST65130 US,DE	<ul> <li>&gt;Inhouse Detection :DAMAGE</li> <li>&gt;Lot size: 1693pcs</li> <li>&gt; Reject Qty: 70pcs</li> <li>&gt; Rejection Rate: 4.13%</li> </ul>	

## **II. IMMEDIATE ACTION**

	Target Date:	Person In-charge				
hing operator report to the subleader that the item was	JULY 27 2023	Sub-leader and Die cut operator				
III. CAUSE ANALYSIS:						
Damaged occured during manual detaching process.						
Damaged encountered due to accidentally cut of edge part of board/panel instead of scrap part. Note: The item to be manually detach was stack in flip flop (Light Model).						
The operator in-charge mislook the cutting portion.						
Standard quantity of removing scrap was not followed by the in-charge operator.						
IV. ACTION PLAN:						
	ALYSIS: Damaged occured during manual detaching process. Damaged encountered due to accidentally cut of edge par Note: The item to be manually detach was stack in flip flo The operator in-charge mislook the cutting portion. Standard quantity of removing scrap was not followed by	JULY 2/ 2023         JALYSIS:         Damaged occured during manual detaching process.         Damaged encountered due to accidentally cut of edge part of board/panel instead of scrap part.         Note: The item to be manually detach was stack in flip flop (Light Model).         The operator in-charge mislook the cutting portion.         Standard quantity of removing scrap was not followed by the in-charge operator.				


-	1	Generate OPL (One Point Lesson) for the standard stacking of Light Models prior inline manual detaching process.	PIC: Production IE Target Date: August 5, 2023
:	2	Re-educate the operator in-charge regarding the proper detaching process of items and proper placing of detach item in the wip area. Reference: OPL (One Point Lesson) for the standard quantity of removing scrap.	PIC: Production IE Target Date: August 5, 2023



POST SIGNAGE AT DIE-CUT 3



ONE POINT LESSON



# ATTENDANCE SHEET