## KANEPACKAGE PHILIPPINE INC.

No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Teleph Fax No

# **INVESTIGATION REPORT**

phone No. (049) 545-7166 to 69 No. (049) 545-6302	Prepared By:	Check By:	Approved By:	
12 Dec 21	K.N.ACUIN	N. CEPEDA	R. MIRANDA	
<u>12-Dec-31</u>	QA-IE/ Prodn IE	QA/ Prodn SV	KPLIMA Operations Gen. Mngr.	

### **DOCUMENT REVIEW**

5M REVIEW		DOCUMENT REVIEW				
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		□ With Revision <sup>☑</sup> No Revision	K.N.ACUIN	N/A
MATERIAL	No Changes	Work Instruction	230811	☑ With Revision □ No Revision	K.N.ACUIN	230831
METHOD	No Changes	Process Flow	250811	□ With Revision □ No Revision	K.N.ACUIN	N/A
ENVIRONMENT	No Changes	Forms	]	$\square$ With Revision $\square$ No Revision	K.N.ACUIN	N/A

#### **I. PROBLEM DESCRIPTION**

DATE:

1.1. ISSUE:					
	SCRATCHES				
<b>1.2. ITEM DESCRIPTION:</b>	.2. ITEM DESCRIPTION:				
PART CODE:	516378500				
PART NAME:	LIME 2 FB ICB FOR AMERICA				
1.3. BACKGROUND:					
GOOD	NG	DETAILS: > LOT QTY: 226EA > <i>REJECT QTY: 14EA (6.19%)</i> > JO#: 041944 > MINOR REJECT/ IN HOUSE DETECTION			

#### **II. IMMEDIATE ACTION**

ACTION ITEMS	Target Date:	Person In-charge
RE -ORIENTATION THE INVOLVED OPERATORS REGARDING THE SCRATCHES ENCOUNTERED	230815	IE STAFF

#### **III. CAUSE ANALYSIS:**

WHY 1:	SCRATCHES ENCOUNTERED ON ITEM CODE 516378500 LIME 2 FB ICB FOR AMERICA DURING PROCESS AT SEMI AUTO GLUING MACHINE 4
WHY 2:	DURING RUNNING, THE UPPER BLUE FLAP OF THE PANEL SCRAPED AGAINST THE DELIVERY CONVEYOR THAT CAUSE SCRATCHES
WHY 3	OPERATOR PULL THE ENTIRE SET OF CARTON BOXES, SCRATCHING THE BOTTOM ITEM AT SENDING CONVEYOR.
WHY 4:	OPERATOR FAILED TO WAIT THE ITEM TO PASS IN CLOSEST TO HIM. NOTE: THE OPERATOR IS UNDER TRAINING
WHY 5:	

#### **IV. ACTION PLAN:**

#### **V. EVIDENCES:**

1	EDUCATE THE CATCHER OPERATOR THE PROPER HANDLING OF THE ITEMS WHEN GETTING THE	230829
1	ITEMS IN THE CONVEYOR	PIC : IE STAFF