KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69

NOVEMBER 14, 2023

Fax No. (049) 545-6302

INVESTIGATION REPORT

	61 1 5	
Prepared By:	Check By:	Approved By:
•		
K.DIAZ	N. CEPEDA	R. MIRANDA
OA IE/ Drada IE	OA / Drodn CV	I/DLIMA Operations Con Maga
OA-IE/ Prodn IE	OA/ Prodn SV	KPLIMA Operations Gen. Mngr.

5M	REVIEW	DOCUMENT REVIEW				
MAN	No Changes	Affected Document:	Date Reviewed:	Disposition:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		With Revision No Revision	K. DIAZ	N/A
MATERIAL	No Changes	Work Instruction	231114	With Revision No Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow	231114	With Revision No Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		With Revision No Revision	K. DIAZ	N/A

I. PROBLEM DESCRIPTION

1.1. ISSUE:			
	SCRATCHES		
1.2. ITEM DESCRIPTION:			
PART CODE:	516378900		
PART NAME:	LIME 2 MB		

1.3. BACKGROUND:

PICTURE



DETAILS:

>Inhouse Detection: SCRATCHES

>Lot size: 585pcs > Reject Qty: 40pcs >Rejection Rate: 6.84%

PROCESS FLOW OF THE ITEM







FEEDING AREA



CUTTING AREA



STRIPPING AREA



DELIVERY AREA

IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
THE SUBLEADER OF SEMI AUTO INFORM THE DIECUT OPERATORS THAT THE ITEM HAVE SCRATCHES AND CONDUCT A MEETING		PIC: OPERATOR AND SUBLEADER

III. CAUSE ANALYSIS:

WHY 1:	WHY SCRATCHES OCCURRED ON THE ITEM? SCRATCHES OCCURRED DURING IN THE DELIVERY WHEN OPERATOR GETTING OF THE ITEM.	
WHY 2:	WHY THE OPERATOR ENCOUNTERED SCRATCH WHEN GETTING THE ITEM? BECAUSE THE DELIVERY STEEL TABLE HAVE SCRATCHES ON IT.	ESON Version 100

KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna

DATE:

Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302

NOVEMBER 14, 2023

Prepared By:	Check By:	Approved By:

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:
K.DIAZ	N. CEPEDA	R. MIRANDA
QA-IE/ Prodn IE	QA/ Prodn SV	KPLIMA Operations Gen. Mngr.

	QA 12/ 110dil 12 Qiyi 110dil	Ri EINA Operations dent milgr.
WHY 3:	WHY THE DELIVERY STEEL TABLE HAVE SCRATCHES? WHEN THEY ENCOUNTERED UNCUT ITEMS, THE OPERATOR REWORK THE ITEM IN THERE USING CUTTER AND THEY DIDN'T KNOW THAT THE TABLE WAS SHARPENED.	
WHY 4:		

IV. ACTION PLAN: V. EVIDENCES:

CONDUCT A MEETING AND RE-EDUCATE THE OPERATORS ABOUT THE ISSUE AND FOR THE REWORK ITEMS THEY ARE NOT ALLOWED ON THE STEEL TABLE TO REWORK. PIC: IE STAFF/LINELEADER/OPERATOR TARGET DATE: NOV 14, 2023 THE OPERATOR SCRUB THE STEEL TABLE USING SANDPAPER (GWS 1500) GREENFIELD PIC: SUBLEADER/OPERATOR TARGET DATE: NOV 14, 2023