KANEPACKAGE PHILIPPINE INC. No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna Telephone No. (049) 545-7166 to 69 Fax No. (049) 545-6302 DATE:

JANUARY 10, 2024

INVESTIGATION REPORT

Prepared By:	Check By:	Approved By:
for known	N/ CEPEQA	(AK MYUNUK)
QA-IE/ Prodn IE	QA/ Prodn \$V	KPLIMA Operations Prod/Mngr)

			- Constitution				1/ 0	
5	M REVIEW		DOCUMENT REVIEW					
MAN	No Changes	Affected Document:	Date Reviewed:		Disposition	on:	PIC:	Target Date:
MACHINE	No Changes	Procedure Manual		0	With Revision	☑ No Revision	K. DIAZ	N/A
MATERIAL	No Changes	Work Instruction	240110	а	With Revision	☑ No Revision	K. DIAZ	N/A
METHOD	No Changes	Process Flow		0	With Revision	No Revision	K. DIAZ	N/A
ENVIRONMENT	No Changes	Forms		0	With Revision	☑ Na Revision	K. DIAZ	N/A

I. PROBLEM DESCRIPTION

1.1. ISSUE:	
	INCOMPLETE PROCESS (GLUING)
1.2. ITEM DESCRIPTION:	
PART CODE:	515958400
PART NAME:	CHARON CARTON BOX
1.2 PACKEDOUND	



- >Inhouse Detection: INCOMPLETE PROCESS
- >Lot size: 400 pcs > Reject Qty: 400 pcS > Rejection Rate: 100%

IMMEDIATE ACTION

ACTION ITEMS	Target Date:	Person In-charge
ODUCT MEETING TO THE OPERATOR	240110	IE STAFF & LINE LEADER

III. CAUSE ANALYSIS:

WHY 1:	WHY THE INCOMPLETE PROCESS OCCURRED ON J.O NUMBER 049749 WITH ITEM CODE 515958400 (CHARON INDIVIDUAL BOX)? INCOMPLETE PROCESS OCCURRED AFTER THE MANUAL DETACHING PROCESS	
WHY 2:	WHY DO INCOMPLETE PROCESS OCCURRED AFTER THE MANUAL DETACHING? THE OPERATORS WERE CONFUSED ON THE APPERANCE OF THE ITEM THAT IT LOOKS LIKE A ACCESSORY	
WHY 3:	WHY THE OPERATOR IS CONFUSED TO THE NEW ITEM? THE OPERATOR FAILED TO CHECK THE ATTACH J.O AND DRAWING	
WHY 4:	WHY THE OPERATOR FAILED TO CHECK THE J.O AND DRAWING? NO PROPER ORIENTATION ON THE NEW ITEM	

IV. ACTION PLAN:

V. EVIDENCES:

1	> HAVE AN ORIENTATION WITH THE OPERATORS BEFORE THEY WORK ON THE NEW ITEM > USE THE NEW SYSTEM (NETSUITE) TO AVOID BY PASSING OF NEXT PROCESS	PIC: IE STAFF/LINELEADER/OPERATOR TARGET DATE: JANUARY 10, 2024
		8