## Investigation Report for Scoring of CBMP 3CB-0059-000

CONTROL No:	IRF -	0025		REJECT PERCENTAGE:	
REJECT QTY:	313	LOT QTY:	2500		12.52%

DIRECT CAUSE	W1	NEED EXTRA CAREFUL TO DETACH THIS ITEM SINCE THE SCORING ACCEPTABLE ON OTHER ITEMS IS REJECTED IN CBMP 3CB.
	W2	PULLING FORCE WAS APPLIED ON ITEM DURING DETACHING PROCESS.
	W3	WORK INSTRUCTION FOR THE REMOVAL OF TRIMMINGS OF DIECUTTED BOARD WAS GENERAL TO ALL ITEMS.

## **PRODUCTION ACTION PLAN**

IMMEDIATE ACTION	CONDUCT AWARENESS ORIENTATION REGARDING THE ISSUE DURING PRODUCTION ASSEMBLY	PIC:	PRODUCTIO N LEADER	TARGET DATE:	250116
CORRECTIVE ACTION	REVISION OF DETACHING WORK INSTRUCTION (INCLUSION OF NOTE FOR PROPER DETACHING OF CBMP ITEMS)	PIC:	PRODUCTIO N IE	TARGET DATE:	250131

PREPARED BY:

APPROVED BY:

GERALD DE GUZMAN
PROD SUPERVISOR

REXEL ALMARIO PROD MANAGER