

Investigation Report for Bursting of CBMP 3CB-0059-000 Partition

CONTROL No:	IRF - 0050			REJECT PERCENTAGE:	4.35%
REJECT QTY:	174	LOT QTY:	4000		

DIRECT CAUSE	W1	UNEVEN EJECTOR PRESSURE.
	W2	INCONSISTENT USAGE OF EJECTOR SPONGE
	W3	NO ESTABLISHED STANDARD SOLUTION TO AVOID BURSTING

PRODUCTION ACTION PLAN

IMMEDIATE ACTION	REAYOUT OF THE BLADE	PIC:	Production Leader & Tooling	TARGET DATE:	250331
CORRECTIVE ACTION	ESTABLISH STANDARD USAGE OF EJECTOR SPONGE ACCORDING TO CITO'S TRAINING	PIC:	Production & ME	TARGET DATE:	250415

PREPARED BY:

GERALD DE GUZMAN
PROD SUPERVISOR

APPROVED BY:

REXEL ALMARIO
PROD MANAGER