KANEPACKAGE PHILIPPINE INC.
No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

■ Inhouse Detection ☐ Customer Claim

Control No.: IRF-23-06-0047 Date Issued: 10-Jun-23

Customer	EPPI	Attention To	NOEMI CEPEDA
Item Code	516001400	Department	KPLIMA- PRODUCTION
Item Description	Lionel PG FGL	Date of Detection	07-Jun-22
Job Order Number	37792	Section Detected	INLINE QA

ILLUSTRATION OF THE PROBLEM

☐ Major ■ Minor



Lot Quantity (pcs.)	Reject Quantity (pcs.)	Reject Percentage
904	112	12.39%

Nature of Defect:

SCRATCHES

ITEM SHOULD BE IN GOOD CONDITION; NO OCCURRENCE OF SCRATCHES

Actual:

SCRATCHES ENCOUNTERED ON UPPER FLAP CLASS B
(PLEASE SEE ATTACHED PICTURE)

NO. OF OCCURRENCE	DISPOSITION	AREA OF OCCURRENCE / ORIGIN	CONTENT
■ First	☐ Hold	☐ Slotter ■ Gluing	☐ Material
☐ Recurrence	☐ Special Acceptance	☐ EQOS ☐ Vertical	☐ Dimension
No.:	☐ For Rework	☐ Diecut ☐ Others:	☐ Appearance
Date:	■ Reject / Disposal	☐ Detaching	■ Process / Method

Issued by	Checked by	Approved by	Received by (Receiving Section)
C. Arevalo QA-IE Staff	G. Magsino QA Supervisor	QA Asst. Manager	N. Cepeda Head/ Supervisor

I. INVESTIGATION / ANALYSIS

	DIRECT CAUSE: (Analyze the reason of occurrence, why it happened?)	INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)
System / Training	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:
Design / Toolings	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:
Process / Material	Why 1: Why 2: Why 3: Why 4: Why 5:	Why 1: Why 2: Why 3: Why 4: Why 5:

KANEPACKAGE PHILIPPINE INC.
No. 5 Ring Road LISP II, Brgy. La Mesa, Calamba City, Laguna
Telephone No. (049) 545-7166 to 69
Fax No. (049) 545-6302

INVESTIGATION REPORT FORM (IRF)

FINAL CONCLUSION

OCCURRENCE ROOTCAUSE	OUTFLOW ROOTCAUSE

IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)	CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)

A. Sorting Result

	Location	Total Stock	NG	Total Good
RM				
WIP				
FG				

B. Orientation

Date		Time	
Title			
Attendees			

C. Reworking

Rework Quantity	
Total Good	
Rework Percentage (Good)	

Actions to be done to eliminate recurrence		Who / When
System		
Design / Tools		
Process		

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)

Date Conducted:_____ PIC:_____

Identified Rootcause	Recommendation

III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)

	Checked by	Date	Implemented?	Remarks
1st Verification of Action			[ ] Yes [ ] No	
2nd Verification of Action			[ ] Yes [ ] No	
3rd Verification of Action			[ ] Yes [ ] No	
Effectiveness of Action			[ ] Yes [ ] No	

Note: If no same defects / problems occurs for 5 consecutive deliveries, corrective action is considered effective / closed. If the same problem occurs within 5 consecutive deliveries or 3rd verification of action still not yet implemented, Investigation Report shall be re-issued to the affected department to provide new improvement action.

IV. CLOSURE

Status:	Remarks:	Approved by:		Process Owner Acknowledgment: (Receiving Section)	
☐ Closed ☐ Still Open ☐ Re-issue IRF	Initial requirement of EPPI= 168 pcs. No available RM Stocks of SF Next Plan: Possible December 2023	QA Supervisor Date:	QA Asst. Manager Date:	Line Leader Date:	Department Head Date: