KAR	MEDACKAC	E PHILIPPINE INC.	INVESTIGA	ATION RI	<b>EPORT</b>	FORM (IRF)	
No. 5 R	Ring Road LISP II, Bro	gy. La Mesa, Calamba City, Laguna	Control		Date Issued		
	one No. (049) 5457-7 . (049) 545-6302	7166 to 69	0019		241011		
Customer	BROTHER INDUS	STRIES PHILIPPINES, INC.	Attention To	WEENA APAL	.LA		
Item Code DO2J9E001			Department	PRODUCTION	J		
Item Description			Date of Detection				
	Order Number   IO24-M-01616-7						
,	]	DF THE PROBLEM	Section Detected QA SCREENING 2				
	LEOSTRATION	THE PROBLEM	Lot Quantity (pcs	Reject (	Oty (pcs)	Reject %	
			2650		00	3.77	
IOUOT G	brother at your side	ASSESSED PROCESSED PROCESS	Nature of Defect:			3.77	
P-TOUCI		P-TOUCH P-TOUCH					
		x3 x3		DE	NT		
			Requirement:				
			No dent mark on class A surface				
	X 3 gr		Actual				
ACTUAL: Wit		nark	Dent mark on class A surface				
REQUIREMENT: No dent mark  NO. OF OCCURENCE DISPOSITION			AREA OF OCCURENCE / ORIGIN CONTENT				
First	CONCINCE	Hold	Slotter Gluing Material				
	Recurrence No.: 1 Special Acceptance		EQOS Vertical			Dimension	
		For Rework	Diecut	Others		Appearance	
	Date.: 241008	Reject / Disposal	Detaching			Process / Method	
Issued by Checked by			Approved		Received by (Receiving Section)		
LESTER JOHN DI	OSO   241011	CHARLENE JAN MARIE FLORES   241011					
DIRECT CAUSE: (A	nalvze the reasor	I. INVESTIGATION  of occurence, why it happened?)	/ ANALYSIS				
System / Training	,	. or occurrence, may to mappenear,					
Design / Toolings							
Jesign, reemigs							
Process / Material							
FIUCESS / Material							



## **INVESTIGATION REPORT FORM (IRF)**

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)									
Syste	m / Trai	ining							
Design / Toolings									
Process / Material									
FINAL CONCLUSION									
CORRI	ECTIVE	ACTION: (Action	ns to be done	to ensure	that the prob	lem will not happ	en again)	WHO / WHEN	
IMME	DIATE A	CTION: (Action	to be done to	contain/ te	emporary cor	rect the problem	found)		
A. Sorting Result C. Reworking									
		Location	Total Stock	NG	Total Good	Rework Quantit	Rework Quantity n/a		
RM		n/a	0	0	0	Total Good		0	
WIP		n/a	0	0	0				
FG		n/a	0	0	0	Rework PPM (Good)		0	
B. Orientation									
Date 2024-11-06						Time		13:11	
Title		Brother J9E redu	ice the standai	rd palletizing	quantity of thi	s item to 300pcs (7	75 x 4) per caster palle	t.	
Attendees SD1800 operators									
Prepared By:						Approved By:			
GERALD DE GUZMAN   241128						REXEL ALMARIO   250205			
						Department Head			



Closed IRF

## **INVESTIGATION REPORT FORM (IRF)**

II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)									
Date Conducted: 2024-10-0	I	PIC: L. Dioso							
lo				Recommendation					
'			Reduce the palletizing quantity from 500 pcs to 300 pcs to minimize pressure and potential deformation.						
III. CORRECTIVE ACTIO	N VERIFICATION (To b	e filled out b	by QA	In-charge)					
	Checked By:	Date	Im	plemented?	Running	JO Number	Date	NG Qty	Lot Qty
1st Verification of Action	L. Dioso	2024-10-07	[/]Yes [ ]No		1st	JO24-M-01616-7	241007	0	2650
2nd Verification of Action			[ ] Yes [ ] No		2nd	JO24-M-01616-8	241010	0	2000
3rd Verification of Action			[ ] Yes [ ] No		3rd	JO24-M-01616-10	241012	0	2600
Effectiveness of Action			[ ]	Yes [ ] No	4th	JO24-M-01616-12	241017	0	2000
Remarks: >Standard palletizing quantity has been revised from 500 pcs to caster pallet for brother D02J9E001 item. >Operators was oriented regarding the changes of palletizing standard of				5th	JO24-M-01616-13	241019	0	2000	
IV. CLOSURE									
Status Remarks									
Classed IDE	No dent-related rejects were observed in five (5) consecutive production runs after implementing corrective								

Appro	ved by:	Process Owner Acknowledgment: (Receiving Section)			
MICHAEL CASILLANO   250424 08:02	KOHEI ISHII   250425 09:51	GERALD DE GUZMAN   250506 02:30	REXEL ALMARIO   250507 11:25		
QA Head	Top Management	Line Leader	Department Head		
Date: 25252525-04-24	Date: 25252525-04-25	Date: 25252525-05-06	Date: 25252525-05-07		

actions.