	NEPACKAG	INVESTIGATION REPORT FORM (IRF)								
Telepho	Ring Road LISP II, Bro one No. (049) 5457-7	Control	No.:	Date Issued						
Fax No	. (049) 545-6302		0032		241123					
Customer	BROTHER INDUS	TRIES PHILIPPINES, INC.	Attention To WEENA APALLA							
Item Code	D02J9E001		Department	PRODUCTION						
Item Description	PRINTED CARTO	N (X3) N10 US COC	Date of Detection	241116	1116					
lob Order Number	JO24-M-01809-1	1	Section Detected QA SCREENING							
ı	LLUSTRATION C	OF THE PROBLEM								
		Lot Quantity (pcs) Rejec		Qty (pcs)	Reject %					
		2000		.9	0.95					
brother Approx	Jeutona brother	P-TOU	Nature of Defect:							
P-TOUCH	P-TOUCH	•	OIL STAIN							
PROCTICITALISE X3	х3		Requirement:							
		x 3 !-	Acceptable small spot is 2mm x 3mm only							
ACTUAL: Wit	h oil stain up te	o 3mm x 275mm	Actual							
REQUIREMEN only		With oil stain up to 3mm x 275mm								
NO. OF OC	CURENCE	DISPOSITION	AREA OF OCCURENCE / ORIGIN CONTENT							
First		Hold	Slotter Gluing		Material					
Recurrence I	No.:1	Special Acceptance For Rework	EQOS Diecut	Vertical Others	' ,					
1	Date.: <u>241116</u>	Reject / Disposal	Detaching	Others		Process / Method				
Issued	d by	Checked by	Approved							
LESTER JOHN DI	OSO 241123	CHARLENE JAN MARIE FLORES 241125	MICHAEL CASILLA	NO 241126	GIN CONTENT Material Dimension Appearance					
		I. INVESTIGATION	/ ANALYSIS							
	nalyze the reasor	of occurence, why it happened?)								
System / Training										
Design / Toolings										
Process / Material										



INVESTIGATION REPORT FORM (IRF)

Department Head

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)											
Syste	m / Trai	ning									
Desig	n / Tool	ings									
Proces	ss / Mat	terial									
FINAL CONCLUSION											
CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again) WHO / WHEN											
IMME	DIATE A	CTION: (Action	to be done to	contain/ te	emporary cor	rect the problen	n found)	•			
A. Sort	ing Resu	ult				C. Reworking					
		Location	Total Stock	NG	Total Good	Rework Quantity		n/a			
RM		n/a	0	0	0	Total Good		0			
WIP		n/a	0	0	0						
FG		n/a	0	0	0	Rework PPM (Go	ood)	0			
B. Orie	ntation										
Date			2024-1	2-05		Time	08:16				
Title		Production Week	ly Assembly M	eeting							
Attend	Attendees All Production										
Prepared By:						Approved By:					
GERALD DE GUZMAN 250128						REXEL ALMARIO 250205					



Date: 25252525-05-23

Date: 25252525-04-25

INVESTIGATION REPORT FORM (IRF)

Date: -

II. QA ROOTCAUSE VEF	RIFICATIO	ON (To be fille	ed out by QA	In-cha	arge)										
Date Conducted: 2025-04-03					PIC: L. Dioso										
Identified Rootcause Excessive oil applied to the glue applicator during the Daily Maintenance Checklist (DMC) dripped during mass production. Insufficient checkpoints on Daily Maintenance Checklist, checking of Glue Applicator for oil leaks is not included.					Recommendation										
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)															
	Che	ecked By:	Date	Im	plemen	ted?	Running	JO Nui	mber	Date	NG Qty	Lot Qty			
1st Verification of Action	L	. Dioso	2025-04-03	[/]	Yes [] No	1st	JO25-M-0	1159-4	250403	0	1000			
2nd Verification of Action				[]	Yes [] No	2nd	JO25-M-0	1159-6	250405	0	1400			
3rd Verification of Action				[]	Yes [] No	3rd	JO25-M-0)1159-8	250407	0	2000			
Effectiveness of Action				[]	Yes [] No	4th	JO25-M-0)1159-9	250408	0	1100			
Remarks: SA2600 Daily Machine Checklist has been revised to include oil the glue applicator and is now in use. Operators have been informed of the							5th	JO25-M-0	1159-11	250411	0	1200			
			IV	/. CLO	SURE										
Status						Remarks									
Still Open No encountered oil stain for the last five production running.															
	Approv	ed by:				Proces	ss Owner A	cknowledg	ıment: (R	leceiving S	Section)				
MICHAEL CASILLANO 2 10:01		250523 02:41	L	GERA		GUZMAN 250603 18:42		N/A							
OA Head		Ton Ma	anagement	Line Leader			Department Head								

Date: 25252525-06-03