KAN	IEDACKAG	E PHILIPPINE INC.	INVESTIGATION REPORT FORM (IRF)						
) No. 5 R	ting Road LISP II, Bro	Control N			Date Issued				
	. (049) 545-6302	0040			241226				
Customer	CANON BUSINES	Attention To REXEL ALMARIO							
Item Code	3CB-0007-000/3	CB-0008-000							
Item Description			Date of Detection 241216						
Job Order Number	JO-F-24-1149-2,	Section Detected OA SCREENING							
1	LLUSTRATION C	OF THE PROBLEM							
·			Lot Quantity (pcs	Reject (	Qty (pcs)	Reject %			
			1000		22	22.20			
1 -	1	again and a second	Nature of Defect:						
			SCORING						
		1 -	Requirement:						
			NO SCORING						
<u> </u>		\_ <u>-</u>	Actual						
3CB-000	WITH SCORING								
NO. OF OCCURENCE DISPOSI		DISPOSITION	AREA OF OCCURENCE / ORIGIN CON			CONTENT			
First		Hold	Slotter	Gluing		Material			
Recurrence I	No.:1	Special Acceptance For Rework	EQOS Vertical			Dimension			
Date.: 241216		Reject / Disposal	Diecut  Detaching	Others DETACH	HING	Appearance Process / Method			
Issued	d bv	Checked by	Approved	l bv	Received by (Receiving Section)				
ERIKA ASIS		CHARLENE JAN MARIE FLORES   241226	MICHAEL CASILLANO   241227		GERALD DE GUZMAN   250113				
	·	I. INVESTIGATION /		•		·			
DIRECT CAUSE: (Analyze the reason of occurence, why it happened?)									
System / Training									
Design / Toolings Process / Material									

W1 PULLING FORCE WAS APPLIED ON ITEM DURING DETACHING PROCESS. r nW2 WORK INSTRUCTION FOR THE REMOVAL OF TRIMMINGS OF WHY 1: DIECUTTED BOARD WAS GENERAL TO ALL ITEMS (NEED EXTRA CAREFUL TO DETACH THIS ITEM SINCE THE SCORING ACCEPTABLE ON OTHER ITEMS IS REJECTED IN CBMP 3CB).



## **INVESTIGATION REPORT FORM (IRF)**

Department Head

INDIRECT CAUSE: (Analyze the reason of occurrence, why it leaked?)										
Syste	n / Trai	ining								
Desig	ı / Tool	ings								
Proce	ss / Ma	terial								
FINAL CONCLUSION										
CORRECTIVE ACTION: (Actions to be done to ensure that the problem will not happen again)  WHO / WHEN								WHO / WHEN		
Process / Material										
WHY 1: CONDUCT AWARENESS ORIENTATION REGARDING THE ISSUE DURING PROD						URING PRODUCTION	N ASSEMBLY Production Leader // 2025-01-			
WHY 2: GUIDELINES FOR PROPER DETACHING OF ITEMS								Production Leader // 2025-01-31		
IMMEDIATE ACTION: (Action to be done to contain/ temporary correct the problem found)										
A. Sorting Result						C. Reworking				
		Location	Total Stock	NG	Total Good	Rework Quantity	<i>y</i>	n/a		
RM		n/a	0	0	0	Total Good		0		
WIP		n/a	0	0	0					
FG		n/a	0	0	0	Rework PPM (Goo	d)	0		
B. Orie	ntation									
Date 2025-01-16			Time 08:15							
Title	tle Production Weekly Assembly Meeting									
Attend	Attendees All Production									
Prepared By:						Approved By:				
GERALD DE GUZMAN   250304					REXEL ALMARIO   250507					



## **INVESTIGATION REPORT FORM (IRF)**

	1,34 (31 (32 )) 1 (31 ) 1 (31 )											
II. QA ROOTCAUSE VERIFICATION (To be filled out by QA In-charge)												
Date Conducted:	PIC:	PIC:										
Ide	Identified Rootcause				Recommendation							
III. CORRECTIVE ACTION VERIFICATION (To be filled out by QA In-charge)												
	Checked By:	Date	Implemented?	Running	JO Nu	mber	Date	NG Qty	Lot Qty			
1st Verification of Action			[ ] Yes [ ] No	1st								
2nd Verification of Action			[ ] Yes [ ] No	2nd								
3rd Verification of Action	of Action		[ ] Yes [ ] No	3rd								
Effectiveness of Action			[ ] Yes [ ] No	4th								
Remarks:												
				5th								
IV. CLOSUPE												
IV. CLOSURE												
Status			Ne	Remarks								
Still Open												
Approved by:			Proces	Process Owner Acknowledgment: (Receiving Section)								
N/A		N/A		N/A			N/A					
QA Head	Тор М	anagement	Line	Line Leader			Department Head					
Date: -	Date: -		Date: -	Date: -			Date: -					